

# LED Soldering Iron Kit – 40 Watt, 120 V PART NUMBER: SP40NKUS



## **FEATURES**

- Weller Consumer Soldering Iron Kits w/3 LED's
- Three LED lights for limited application shadowing
- Round Co-molded soft grip handle design for easy tip positioning
- Triangular handle area for maximum tip control
- Stainless steel heater construction
- UL listed cUL version available
- Excellent quality consumer iron
- IMPORTANT: Use only original Weller tips



## **SPECIFICATIONS**

Material ID	SP40NKUS
Wattage	40 W
Temperature Range	900°F / 482°C
Voltage Input	120 V
Set	Yes
Supplied Tip(s)	MT10, ST3, ST7
Style Type	Non-temperature Controlled
Packaging	No
Package Length	12.37 in
Package Width	4.87 in
Package Height	1.76 in
Package Gross Weight	0.43 lb
UPC	037103266910
Country of Origin	Mexico
Foreign Trade Code	8515110000



Weller Professional Tools 1000 Lufkin Road Apex, NC 27539 Ph: 919-387-0099

April 23, 2013



## Soldering Tip Maintenance

### **ALWAYS:**

Tin the tip – If not done, tip will oxidize (turn brown or black) and loose heat transfer ability Use distilled water to keep sponge damp (not drenched)

Keep sponge clean

Use the Weller Dry Clean System WDC

Higher Temp = Reduced Tip Life

#### **HOW TO "RENEW" YOUR TIP**

Before tip is oxidized, use the Weller WPB1 polishing bar. When tip is cold lightly polish the tip to remove oxides. Immediately re-tin the tip

In extreme cases of tip oxidation or tip "burnout" use the WPB1 along with tip tinnier. Once tip is renewed, re-tin immediately.

Use the lowest soldering iron temperature possible

#### **SOLDERS & FLUXES FACTS**

The higher tin content in lead free solders attacks the iron plating on soldering tips.

Small diameter wire solder often has Flux voids that cause tip oxidation.

Hard, black smooth coating on tip is burned on flux, not a tip defect.

Water-soluble fluxes are highly corrosive at high temperatures and especially damaging to soldering tips.

Wire solder cored with water-soluble flux used during touch-up and rework procedures result in accelerated tip failure.

No-clean fluxes are usually insufficient to clean normal oxides off soldering tips.



