


## Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350 °C, 100 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

## RECOMMENDED PANEL CUT OUT



	· = =		n				_			_	B			\
	THIS REPR BE PA WRIT		rev.	description	date	name	T'		<b>'</b>   -		part no:	SEE	SHEET 1	
	THIS DRAWIN REPRODUCED BE PASSED OI WRITTEN PER OWNERSHIP	NOT ALT	а	a Original					1 <b>5</b> =6°		131(141300		sh:2/2	
							_	45 8	. ==		151	15K1A15	1 1 1 5 0 6	A3
	SE SE SE	臣					d-old				dwg no:			DIN-
	IAY NOT BE COPIED OR ANY WAY, AND MAY NOT D A THIRD PARTY WITHOUT SION. COPYRIGHT OF CONEC GMBH	CAD DRAWING					norm				RECOMMENDED PANEL CUT D-SUB COMBINATION MALE 2W2CI with threaded insert and hexlocking scr		crew	
							appd.	12.06.14	Lehmer	nkühler			-	
							drawn	11.06.14	Henn	eboel			PANEL CU	T-OUT
	COPIED (ND MAY ARTY WI	NG ING						date	nar	me	title:			
	ED OR AY NOT WITHOUT	BY HAND							dim.	in mm	material: SEE SHEET 1			
							tolerance		1		material:			
Г	동						+al	040000			scale:		3:1	

Downloaded from Arrow.com.