SYMBOL DEFINITION
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.

TOTAL NO OF INSPECTIONS REQUIRED	14
LEF NO. LEF	14

MISSING SYMBOLS
NO MISSING SYMBOL NUMBER

| REVISION HISTORY | | |