



[illegible]

- Marking failures
- Housing material failures
- Spoilt housing
- Stained housing
- Broken contacts (twisted or loosen)

Part number	HM1 W42DTR400H6P
-------------	------------------

Part number	HM1 W42DTR400H6PLF
-------------	--------------------

SEE PRODUCT SPECIFICATION GS-12-446

European Views

rev	ecn no	dr	date
A	-	-	-
B	LS05-001	MLE	2005/03/15
C	LS06-0095	LGO	2006/07/04
D	LS07-0012	MLE	2007/03/27
-	-	-	-
-	-	-	-
-	-	-	-

www.fciconnect.com			surface ISO 1302 		tolerance std ISO 406 ISO 1101		projection 		mm 	
			TOLERANCES UNLESS OTHERWISE SPECIFIED							
Dr	PERRICHOT	24/06/30	ANGULAR	LINEAR	0.X	±0.1	size A3	Scale 2.5		
Eng	LENOIR	2001/01/25			0.XX	±0.1		ECN	LS07-0012	
Chr	LEGARE	2001/01/25			0.XXX	±0.1				
Appr	LEGARE	2001/01/25	Product family				METRAL		Spec ref -	
			METAL STRAIGHT HEADER - 48 WAY SOLDER TAILS/WIDE BODY SP 400				dwg no C-8626-11107		Rev. D	
catalog no			-				CUSTOMER		sheet	of 1