ABP2 SERIES

32350268
Issue I

Board Mount Pressure Sensors

High Accuracy, Compensated/Amplified
2.5 mbar to 20 bar | 250 Pa to2 MPa | 1 inH_2O to 290 psi
Digital or Analog Output, Liquid Media Capable

DESCRIPTION


The ABP2 Series are piezoresistive silicon pressure sensors offering a digital or analog output for reading pressure over the specified full scale pressure span and temperature range. They are calibrated and temperature compensated for sensor offset, sensitivity, temperature effects, and accuracy errors (which include non-linearity, repeatability and hysteresis) using an on-board Application Specific Integrated Circuit (ASIC). Calibrated output values for pressure and temperature are updated at approximately 200 Hz. All products are designed and manufactured according to ISO 9001 standards. The liquid media option includes an additional gel coating to protect the electronics under port P1, which enables use with non-corrosive liquids (e.g. water and saline) and in applications where condensation can occur. The ABP2 Series is available in tube packaging. Pocket tape and reel packaging is available upon request.

APPLICATIONS

- **Medical** — Ventilators/portable ventilators, CPAP, blood analysis, blood pressure monitoring, breast pumps, drug dosing, hospital beds, massage machines, oxygen concentrators, patient monitoring, sleep apnea equipment, urine analyzers, and wound therapy
- **Industrial** — HVAC transmitters, life sciences, material handling, pneumatic control and regulation, process gas monitoring, and valve positioning/positioners
- **Commercial** — Air beds, coffee makers, washing machines, level measurement, dish washers, vacuum cleaners, hand dryers, and rice cookers
- **Transportation** — Air brakes, CNG monitoring, fork lifts, and fuel level measurement

FEATURES

- Total Error Band (see Figure 1):
  - As low as ±1.5 % FSS
- Liquid media option:
  - Compatible with a variety of liquid media
- Long-term stability:
  - As low as ±0.2 % FSS
- Accuracy:
  - As low as ±0.25 % FSS BFSL
- Wide pressure range:
  - 2.5 mbar to 20 bar
  - 250 Pa to 2 MPa
  - 1 inH_2O to 290 psi
- High burst pressures
- Wide operating temperature range of -40°C to 110°C [-40°F to 230°F]
- Calibrated over wide temperature range of -40°C to 110°C [-40°F to 230°F]
- 24-bit digital I^2C or SPI-compatible output
- Ratiometric analog output
- IoT (Internet of Things) ready interface
- Ultra-low power consumption:
  - As low as 0.01 mW typ. average power
  - 1 Hz measurement frequency
- Meets IPC/JEDEC J-STD-020E Moisture Sensitivity Level 2
- REACH and RoHS compliant
- Temperature output available
- NSF-169, LFGB and BPA compliant materials



BPA Free

NSF

PORTFOLIO

Honeywell offers a variety of board mount pressure sensors for use in medical and industrial applications. To view the entire product portfolio, click here.

Honeywell

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

VALUE TO CUSTOMERS

- **Simplifies design-in**
  - Small size saves room on the PC board (PCB), simplifying design in smaller and lower power devices
- **Meets IPC/JEDEC J-STD-020E Moisture Sensitivity Level 2 requirements**
  - Allows avoidance of thermal and mechanical damage during solder reflow attachment and/or repair that lesser rated sensors may incur
  - Allows for unlimited shelf life when stored inside sealed moisture barrier bag
  - Allows for lean manufacturing due to stability and usability shortly after reflow
- **Cost-effective**
  - Small size helps engineers reduce design and manufacturing costs while maintaining enhanced performance and reliability of the systems they design
- **Accurate**
  - Total Error Band (TEB) and wide pressure range enable engineers to optimize system performance by improving resolution and system accuracy
- **Flexible**
  - Supply voltage range, variety of pressure units, types and ranges, output options, and wide operating temperature range simplify use in the application
- **Versatile**
  - Wet-media compatibility, low power, and temperature output options make the sensor a versatile choice for Internet of Things applications

DIFFERENTIATION

- **Application**
  - Specific design ensures suitability for a wide array of customer requirements
- **Digital output**
  - Allows the sensor to be directly plugged into the customer's circuitry without requiring major design changes
- **Total Error Band (see Figure 1):**
  - Provides a more comprehensive measurement of performance over the compensated temperature range, which minimizes testing and calibrating every sensor, thereby potentially reducing manufacturing cost; improves sensor accuracy and offers ease of sensor interchangeability due to minimal part-to-part variation
  - Improves sensor accuracy
  - Offers ease of sensor interchangeability due to minimal part-to-part variation

Downloaded from Arrow.com.

TABLE OF CONTENTS

4 Total Error Band

5 General Specifications

8 Power Consumption and Standby Mode
8 DigOital Output Versions
10 Analog Output Versions
11 Nomenclature and Order Guide
12 High Pressure/High Temperature Introduction
13 High Pressure/High Temperature Nomenclature and Order Guide

15 Pressure Range Specifications

23 Dimensional Drawings

33 1.0 General Information

33 2.0 Pinout and Functionality

33 3.0 Start-Up Timing

33 4.0 Power Supply Requirement

34 5.0 Reference Circuit Design
34 5.1 Digital Output Versions
34 5.2 Analog Output Versions
34 5.3 Bypass Capacitor Use

35 6.0 I2C Communications
35 6.1 I^2C Bus Configuration
35 6.2 I^2C Data Transfer
35 6.3 I^2C Sensor Address
35 6.4 I^2C Pressure and Temperature Reading
36 6.5 I^2C Status Byte
36 6.6 I^2C Communications
37 6.7 I^2C Timing and Level Parameters
38 6.8 Reference Code (Arduino/Genuino Uno) for I2C Interface

39 7.0 SPI Communications
39 7.1 SPI Definition
39 7.2 SPI Data Transfer
40 7.3 SPI Pressure and Temperature Reading
40 7.4 SPI Status Byte
41 7.5 SPI Communications
42 7.6 SPI Timing and Level Parameters
43 7.7 Reference Code (Arduino/Genuino Uno) for SPI Interface

44 8.0 ABP2 Series Calculations
45 8.1 Digital Output Versions
46 8.2 Analog Output Versions

46 9.0 Recommended Pneumatic Sensor Connections
47 9.1 Tubing
48 9.2 O-ring Manifold Designs

Back cover Additional Information

Downloaded from Arrow.com.

TOTAL ERROR BAND

Total Error Band (TEB) is a single specification that includes the major sources of sensor error. TEB should not be confused with accuracy, which is actually a component of TEB. TEB is the worst error that the sensor could experience.

Honeywell uses the TEB specification in its datasheet because it is the most comprehensive measurement of a sensor's true accuracy. Honeywell also provides the accuracy specification in order to provide a common comparison with competitors' literature that does not use the TEB specification.

Many competitors do not use TEB—they simply specify the accuracy of their device. Their accuracy specification, however, may exclude certain parameters. On their datasheet, the errors are listed individually. When combined, the total error (or what would be TEB) could be significant.

Figure 1. Total Error Band




TABLE 1. ABSOLUTE MAXIMUM SPECIFICATIONS[1]

Characteristic	Minimum	Maximum	Unit
Supply voltage (V_{supply}):			
digital output	-0.3	3.6	Vdc
analog output	-0.3	6.0	
Voltage on any pin	-0.3	V_{supply} + 0.3	Vdc
Digital clock frequency:			
I²C	100	400	kHz
SPI	50	800	
ESD susceptibility (human body model)	2	—	kV
Storage temperature range	-40 [-40]	125 [257]	°C [°F]
Soldering time and temperature:			
lead (DIP)	4 s max. at 250°C [482°F]		
peak reflow (SMT, Leadless SMT)	15 s max. at 250°C [482°F]		

[1]Absolute maximum ratings are the extreme limits the device will withstand without damage.

Downloaded from Arrow.com.

TABLE 2. OPERATING SPECIFICATIONS

Characteristic	Analog			Digital			Unit
	Minimum	Typical	Maximum	Minimum	Typical	Maximum	
Supply voltage (V_{supply})[1] **3.3 Vdc** **5.0 Vdc**	 3.0 4.75	 3.3 5.0	 3.6 5.25	 1.8 –	 3.3 –	 3.6 –	Vdc
Current consumption: **I²C sleep/standby mode** **SPI sleep/standby mode**	 – –	 – –	 – –	 3.0 13.0	 33.8 43.8	 211.0 221.0	nA
Power consumption	–	9.5	–	–	3.1	–	mW
Operating temperature range[2]	-40 [-40]	–	110 [230]	-40 [-40]	–	110 [230]	°C [°F]
Compensated temperature range[3]	-40 [-40]	–	110 [230]	-40 [-40]	–	110 [230]	°C [°F]
Startup time[4]	–	–	5	–	–	2.5	ms
Clipping limit for analog version: **Upper** **Lower**	 – 2.5	 – –	 97.5 –	 – –	 – –	 – –	V_{supply}
Update/data rate	–	1000	–	161	204	–	Samples/s
SPI/I²C voltage level: **Low** **High**	 – –	 – –	 – –	 – 80	 – –	 20 –	$\%V_{supply}$
Pull up on SDA, SCL	–	–	–	1	–	–	kOhm
Accuracy[5] **0 to 16 mBar** **16 mBar to 12 Bar**	 –	 –	 ±0.4 ±0.25	 –	 –	 ±0.4 ±0.25	% FSS BFSL[6]
Resolution	0.03 –	– –	– –	– 14	– –	– –	% FSS bits
Temperature output error[7]	–	–	–	–	±5	–	°C

[1] Sensors are not reverse polarity protected. Incorrect application of supply voltage or ground to the wrong pin may cause electrical failure.

[2] **Operating temperature range:** The temperature range over which the sensor will produce an output proportional to pressure.

[3] **Compensated temperature range:** The temperature range over which the sensor will produce an output proportional to pressure within the specified performance limits (see Total Error Band).

[4] **Startup Time:** For analog versions: 5 ms to data ready. For digital versions: 2.5 ms for power up to receive the first measurement command. Refer to Section 3.0, Tables 22, 23 and 26 for further details on communication timing.

[5] **Accuracy:** The maximum deviation in output from a Best Fit Straight Line (BFSL) fitted to the output measured over the pressure range at 25°C [77°F]. Includes all errors due to pressure non-linearity, pressure hysteresis and non-repeatability.

[6] **Full Scale Span (FSS):** The algebraic difference between the output signal measured at the maximum (Pmax.) and minimum (Pmin.) limits of the pressure range (see Figure 2).

[7] **Temperature Output Error:** The error in Temperature Output reading relative to a thermal reference standard over a temperature range of -40°C to 125°C.

Downloaded from Arrow.com.

TABLE 3. ENVIRONMENTAL SPECIFICATIONS	
Characteristic	**Parameter**
Humidity: **all external surfaces** **internal surfaces of liquid media options "T", "V", "G" and "F"** **internal surfaces of dry gases options "N" and "D"**	 0 %RH to 95 %RH, non-condensing 0 %RH to 100 %RH, condensing 0 %RH to 95 %RH, non-condensing
Vibration	15 g, NSF169, BPA Free, LFGB 10 Hz to 2 kHz
Shock	75 g, 6 ms duration
Life[1]	1 million full scale pressure cycles minimum
Solder reflow	J-STD-020-E, MSL2 (see shelf life/floor life)
Shelf life	Unlimited storage life, inside sealed moisture barrier bag
Floor life[3]	1 year floor life, after removal from sealed moisture bag, <30°C & <60 %RH
Certification (silicone gel coating option, Port 1 only)[2]	NSF169, BPA Free, LFGB

[1] Life may vary depending on specific application in which the sensor is utilized.
[2] Sensor materials have been tested and certified for the food safety standards noted.
[3] Floor life, the maximum recommended time period after removal from a moisture barrier bag or dry storage prior to solder reflow. If the maximum recommended floor time is exceeded, parts may require to be baked at 85°C for up to 12 hours prior to solder reflow.

TABLE 4. WETTED MATERIALS[1]			
Component	**Pressure Port 1 (P1)**		**Pressure Port 2 (P2)**
	Dry Gas Option	**Liquid Media Option**	
Ports and covers	High temperature polyamide, 304 SST		High temperature polyamide
Substrate	FR4	—	FR4
Adhesives	Epoxy, silicone	Epoxy, silicone gel, fluorosilicone gel	Epoxy, silicone
Electronic components	Silicon, glass, gold, aluminum	—	Silicon


[1] Contact Honeywell customer service for detailed material information.

TABLE 5. SENSOR PRESSURE TYPES	
Pressure Type	**Description**
Absolute	Output is proportional to the difference between pressure applied and a built-in vacuum reference.
Differential	Output is proportional to the difference between the applied pressure to each port (Port1 - Port2)
Gage	Output is proportional to the difference between applied pressure and atmospheric (ambient) pressure.

TABLE 6. SENSOR OUTPUT AT SIGNIFICANT PERCENTAGES				
Output (%)	**Digital Versions**		**Analog Versions**	
	Counts		**V_{SUPPLY}**	
	Decimal	**Hex**	**3.3 V**	**5.0 V**
0	0	0X000000	0.0	0.0
10	1677722	0X19999A	0.33	0.5
30	5033165	0X4CCCCC	0.99	1.5
50	8388608	0X800000	1.65	2.5
70	11744051	0XB33333	2.31	3.5
90	15099494	0XE66666	2.97	4.5
100	16777215	0XFFFFFF	3.3	5.0

Downloaded from Arrow.com.

Figure 2. Transfer Function for Digital Output Versions




Pressure example 1: Transfer Function A (10% to 90%)

$$\text{Output (\% of } 2^{24} \text{ counts)} = \frac{80\%}{P_{max.} - P_{min.}} \times (\text{Pressure}_{applied} - P_{min.}) + 10\%$$

Pressure example 2: Transfer Function B (30% to 70%)

$$\text{Output (\% of } 2^{24} \text{ counts)} = \frac{40\%}{P_{max.} - P_{min.}} \times (\text{Pressure}_{applied} - P_{min.}) + 30\%$$

Figure 3. Transfer Function for Analog Output Versions



$$\text{Output (V)} = \frac{0.8 \times V_{supply}}{P_{max.} - P_{min.}} \times (\text{Pressure}_{applied} - P_{min.}) + 0.10 \times V_{supply}$$

Downloaded from Arrow.com.

POWER CONSUMPTION AND STANDBY MODE


DIGITAL OUPTUT VERSIONS

The sensor is normally in Standby Mode and is only turned on in response to a user command, thus minimizing power consumption. Upon receiving the user command, the sensor wakes up from Standby Mode, runs a measurement in Active State, and automatically returns to Standby Mode, awaiting the next command. The resulting sensor power consumption is a function of the sampling rate (samples per second) as shown in Tables 7 and 8 and Figures 4 and 5.

TABLE 7. DIGITAL OUTPUT VERSIONS AVERAGE POWER CONSUMPTION AT 1.8 V_{SUPPLY} (ASSUMES COMMAND AA_{HEX})

Sampling Rate (samples per second)	Average Power (mW)	Active Time (ms)	Active Power (mW)	Idle Time (ms)	Idle Power (mW)
Minimum Average Power					
1	0.0068	3.625	1.884	996.375	0.0000054
2	0.0137	7.25	1.884	992.75	0.0000054
5	0.0341	18.125	1.884	981.875	0.0000054
10	0.0683	36.25	1.884	963.75	0.0000054
20	0.1366	72.5	1.884	927.5	0.0000054
50	0.3414	181.25	1.884	818.75	0.0000054
100	0.6829	362.5	1.884	637.5	0.0000054
160	1.0926	580	1.884	420	0.0000054
Typical Average Power					
1	0.0094	4.157	2.248	995.843	0.00006084
2	0.0187	8.314	2.248	991.686	0.00006084
5	0.0468	20.785	2.248	979.215	0.00006084
10	0.0935	41.57	2.248	958.43	0.00006084
20	0.1870	83.14	2.248	916.86	0.00006084
50	0.4673	207.85	2.248	792.15	0.00006084
100	0.9345	415.7	2.248	584.3	0.00006084
160	1.4592	665.12	2.248	334.88	0.00006084
Maximum Average Power					
1	0.0129	4.839	2.588	995.161	0.0003798
2	0.0254	9.678	2.588	990.322	0.0003798
5	0.0630	24.195	2.588	975.805	0.0003798
10	0.1256	48.39	2.588	951.61	0.0003798
20	0.2508	96.78	2.588	903.22	0.0003798
50	0.6264	241.95	2.588	758.05	0.0003798
100	1.2524	483.9	2.588	516.1	0.0003798
160	2.0036	774.24	2.588	225.76	0.0003798

Figure 4. Digital Output Versions Average Power Consumption vs Sampling Rate at 1.8 V_{SUPPLY}




Downloaded from Arrow.com.

TABLE 8 . DIGITAL OUTPUT VERSIONS AVERAGE POWER CONSUMPTION AT 3.3 V_{SUPPLY} (ASSUMES COMMAND AA_{HEX})

Sampling Rate (samples per second)	Average Power (mW)	Active Time (ms)	Active Power (mW)	Idle Time (ms)	Idle Power (mW)
Minimum Average Power					
1	0.0114	3.625	3.134	996.375	0.0000099
2	0.0227	7.25	3.134	992.75	0.0000099
5	0.0568	18.125	3.134	981.875	0.0000099
10	0.1136	36.25	3.134	963.75	0.0000099
20	0.2272	72.5	3.134	927.5	0.0000099
50	0.5680	181.25	3.134	818.75	0.0000099
100	1.1361	362.5	3.134	637.5	0.0000099
160	1.8177	580	3.134	420	0.0000099
Typical Average Power					
1	0.0156	4.157	3.729	995.843	0.00011154
2	0.0311	8.314	3.729	991.686	0.00011154
5	0.0776	20.785	3.729	979.215	0.00011154
10	0.1551	41.57	3.729	958.43	0.00011154
20	0.3101	83.14	3.729	916.86	0.00011154
50	0.7751	207.85	3.729	792.15	0.00011154
100	1.5501	415.7	3.729	584.3	0.00011154
160	2.4800	665.12	3.729	334.88	0.00011154
Maximum Average Power					
1	0.0214	4.839	4.275	995.161	0.0006963
2	0.0421	9.678	4.275	990.322	0.0006963
5	0.1041	24.195	4.275	975.805	0.0006963
10	0.2075	48.39	4.275	951.61	0.0006963
20	0.4144	96.78	4.275	903.22	0.0006963
50	1.0349	241.95	4.275	758.05	0.0006963
100	2.0692	483.9	4.275	516.1	0.0006963
160	3.3103	774.24	4.275	225.76	0.0006963

Figure 5. Digital Output Versions Average Power Consumption vs Sampling Rate at 3.3 V_{SUPPLY}




Downloaded from Arrow.com.

ANALOG OUTPUT VERSIONS (SEE TABLE 9 AND FIGURE 6.)

TABLE 9. ANALOG OUTPUT VERSIONS POWER CONSUMPTION

Vsupply (V)	Active Power (mW)	Minimum Power (mW)	Average Power (mW)	Maximum Power (mW)
2.8	3.36	3.3	3.4	3.5
3.3	4.62	4.4	4.5	4.7
5	9.5	9.1	9.2	9.4
5.5	11	10.9	11.0	11.1

Figure 6. Analog Output Versions Average Power Consumption



Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

Figure 7. Nomenclature and Order Guide

For example, **ABP2DANT001BA2A3XX** defines an ABP2 Series Amplified Basic Pressure Sensor, DIP package, plastic single axial barbed pressure port, liquid media, food-grade silicone gel, no diagnostics, 1 bar absolute pressure range, digital I^2C, address 0x28 output type, 10 % to 90 % of 2^{24} counts (digital) transfer function, 3.3 Vdc supply voltage.

ABP2 D AN T 001BA 2 A 3 XX








Product Series

ABP2	Amplified Basic

Package

D	DIP (Dual Inline Pin)
M	SMT (Surface Mount Technology)
L	Leadless SMT

Pressure Port[1]

	DIP	SMT	Leadless SMT
Plastic	NN No port 	NN No port 	NN No port 
Plastic	AN Single axial barbed port 	AN Single axial barbed port 	AN Single axial barbed port 
Metal	VN Single axial barbless port 	VN Single axial barbless port 	VN Single axial barbless port 
Metal	SN Single axial straight barbless port 	SN Single axial straight barbless port 	SN Single axial straight barbless port 
Plastic	RN Single radial barbed port 	RN Single radial barbed port 	—
Plastic	RR Dual radial barbed ports, same side 	RR Dual radial barbed ports, same side 	—
Plastic	DA Dual axial barbed ports, same side 	DA Dual axial barbed ports, same side 	—

Product Option[2,3,4]

N	Dry gases only, no diagnostics
D	Dry gases only, diagnostics on
T	Liquid media, food-grade silicone gel, no diagnostics
V	Liquid media, food-grade silicone gel, diagnostics on
G	Liquid media, fluorosilicone gel, no diagnostics
F	Liquid media, fluorosilicone gel, diagnostics on

Future

XX	

Supply Voltage[4]

3	3.3 Vdc
5	5.0 Vdc

Transfer Function

A	10 % to 90 % of Vsupply (analog), 2^{24} counts (digital)

Output Type

A	Analog	3	I^2C, Address 0x38
S	SPI	4	I^2C, Address 0x48
0	I^2C, Address 0x08	5	I^2C, Address 0x58
1	I^2C, Address 0x18	6	I^2C, Address 0x68
2	I^2C, Address 0x28	7	I^2C, Address 0x78

Pressure Range

2.5 mbar to 12 bar Absolute		250 Pa to 1.2 MPa Absolute		1 inH_2O to 175 psi Absolute	
001BA	1 bar	100KA	100 kPa	015PA	15 psi
1.6BA	1.6 bar	160KA	160 kPa	030PA	30 psi
2.5BA	2.5 bar	250KA	250 kPa	060PA	60 psi
004BA	4 bar	400KA	400 kPa	100PA	100 psi
006BA	6 bar	600KA	600 kPa	150PA	150 psi
010BA	10 bar	001GA	1.2 MPa	175PA	175 psi
012BA	12 bar				
Differential		**Differential**		**Differential**	
2.5MD	±2.5 mbar	250LD	±250 Pa	001ND	±1 inH_2O
006MD	±6 mbar	600LD	±600 Pa	002ND	±2 inH_2O
010MD	±10 mbar	001KD	±1 kPa	004ND	±4 inH_2O
016MD	±16 mbar	1.6KD	±1.6 kPa	005ND	±5 inH_2O
025MD	±25 mbar	2.5KD	±2.5 kPa	010ND	±10 inH_2O
040MD	±40 mbar	004KD	±4 kPa	020ND	±20 inH_2O
060MD	±60 mbar	006KD	±6 kPa	030ND	±30 inH_2O
100MD	±100 mbar	010KD	±10 kPa	001PD	±1 psi
160MD	±160 mbar	016KD	±16 kPa	005PD	±5 psi
250MD	±250 mbar	025KD	±25 kPa	015PD	±15 psi
400MD	±400 mbar	040KD	±40 kPa	030PD	±30 psi
600MD	±600 mbar	060KD	±60 kPa	060PD	±60 psi
001BD	±1 bar	100KD	±100 kPa		
1.6BD	±1.6 bar	160KD	±160 kPa		
2.5BD	±2.5 bar	250KD	±250 kPa		
004BD	±4 bar	400KD	±400 kPa		
Gage		**Gage**		**Gage**	
006MG	6 mbar	600LG	600 Pa	002NG	2 inH_2O
010MG	10 mbar	001KG	1 kPa	004NG	4 inH_2O
016MG	16 mbar	1.6KG	1.6 kPa	005NG	5 inH_2O
025MG	25 mbar	2.5KG	2.5 kPa	010NG	10 inH_2O
040MG	40 mbar	004KG	4 kPa	020NG	20 inH_2O
060MG	60 mbar	006KG	6 kPa	030NG	30 inH_2O
100MG	100 mbar	010KG	10 kPa	001PG	1 psi
160MG	160 mbar	016KG	16 kPa	005PG	5 psi
250MG	250 mbar	025KG	25 kPa	015PG	15 psi
400MG	400 mbar	040KG	40 kPa	030PG	30 psi
600MG	600 mbar	060KG	60 kPa	060PG	60 psi
001BG	1 bar	100KG	100 kPa	100PG	100 psi
1.6BG	1.6 bar	160KG	160 kPa	150PG	150 psi
2.5BG	2.5 bar	250KG	250 kPa	175PG	175 psi
004BG	4 bar	400KG	400 kPa		
006BG	6 bar	600KG	600 kPa		
008BG	8 bar	800KG	800 kPa		
010BG	10 bar	001GG	1 MPa		
012BG	12 bar	1.2GG	1.2 Mpa		

[1] The "DA" Pressure Port is only available with Product Options "N" and "D". The "DA" Pressure Port is available in standard listings with pressure ranges up to 400 mbar | ±160 mbar. For higher pressure ranges, please contact the technical support team.

[2] Product Options "N" and "D" are only available with gage pressure ranges 6 mbar to 40 mbar | 600 Pa to 4 kPa | 2 in-H_2O to 20 in-H_2O and differential pressure ranges ±2.5 mbar to ±25 mbar | ±250 Pa to ± 2.5 kPa | ±1 in-H_2O to ±10 in-H_2O.

[3] Product Options "T" and "V" are only available with pressure ranges 60 mbar I 6 kPa | 1 psi gage and ±40 mbar | ±4 kPa | 1 psi differential and above.

[4] 5 Vdc supply voltage and diagnostic options are only available with analog output listings. They are not available with digital output listings.

[5] Ultra low pressure ranges less than 1 psi or 60 mbar are not available as standard listing in leadless package, please contact the technical support team for such requests.

[6] ABP2 series pressure sensors are piezo-resistive based which are sensitive to change in light intensity. These semiconductor materials when exposed to light, change the output resulting in sensor offset voltage. For applications where direct exposure to light is possible, we recommend Flurosilicone gel listings which are less susceptible to light transmitting to the sense die.

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES | HIGH PRESSURE, HIGH TEMPERATURE

ABP2 HP/HT pressure sensors are specifically designed for use demanding applications where the sensor can be used to measure pressure up to 20 bar/300 psi and may be exposed to high pressure, high temperature and vibration at the same time for a prolonged period of time. The specialised layer of shock-proof adhesive around the housing is precision engineered to provide additional robustness within demanding applications and environments. ABP2 HP/HT sensor supports over pressure pressures up to 30 bar (450 psi), burst pressures greater than 40 bar (600 psi) and additional robustness to pressure spikes, vibration and shocks.

ABP2 HP/HT sensors are offered with a choice of three differed port options and three different package options, which are intended to be installed within a manifold design. ABP2 HP/HT sensors can be used with dry gases or liquids and are offered with a choice silicone food grade or flurosilicone gel to provide extensive media compatibility supporting a wide range of applications.

The Honeywell ABP2 HP/HT sensors are fully calibrated, temperature compensated and are offered with a choice of analogue or digital (SPI, I²C) outputs. All products are designed and manufactured according to ISO 9001 standards and are manufactured to the highest standards. Our ABP2 HP/HT sensors are designed to work at the high pressure and high temperature continuously with a 100 % duty cycle. Standard ABP2 parts should only be exposed to high pressure and high temperature at the same time for short periods of time.

FEATURES

- High operating pressure up to 20 bar/300 psi
- High burst pressure >40 bar/600 psi
- High accuracy: as low as 1.5 % TEB
- Extended media compatibility
- Ultra-small factor
- Low power consumption
- Meets IPC/JEDEC J-STD-020E-MSL 2
- RoHS and REACH compliant materials
- Compensated temperature range: 0°C to 85°C
- Operating temperature range (1 bar to 12 bar): -40°C to 110°C
- Operating temperature range (13 bar to 20 bar): -40°C to 85°C

APPLICATIONS

Industry	Application
Medical	Medical gas pressure line monitoring, high pressure inflation devices, medial compressors, oxygen concentrators
Industrial	Digital and wireless pressure transducer, Air compressors, pneumatic control process gas monitoring, and valve positioning/positioners
Commercial	Water pumps, air beds, coffee makers, washing machines, level measurement, dish washers, vacuum cleaners, hand dryers, rice cookers
Transportation	Transportation air brakes, CNG monitoring, forklifts

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES | HIGH PRESSURE, HIGH TEMPERATURE

Figure 8. Nomenclature and Order Guide (High Pressure/High Temperature)

For example, **ABP2DSXT012BG2A3XX** defines an ABP2 Series Amplified Basic Pressure Sensor for High Pressure & High Temperature Application, DIP package, metal single axial straight barbless port with additional adhesive, liquid media, food-grade silicone gel, no diagnostics, 12 bar gauge pressure range, digital I²C, address 0×28 output type, 10 % to 90 % of 2^{24} counts (digital) transfer function, 3.3 Vdc supply voltage.

ABP2 D SX T 012BG 2 A 3 XX





Product Series

ABP2	Amplified Basic

Package

D	DIP (Dual Inline Pin)
M	SMT (Surface Mount Technology)
L	Leadless SMT

Pressure Port[1,2]

	DIP	SMT	Leadless SMT
Plastic	NX No port 	NX No port 	NX No port 
Metal	VX Single axial barbless port 	VX Single axial barbless port 	VX Single axial barbless port 
Metal	SX Single axial straight barbless port 	SX Single axial straight barbless port 	SX Single axial straight barbless port 

Product Option[3]

T	Liquid media, food-grade silicone gel, no diagnostics
G	Liquid media, fluorosilicate gel, no diagnostics

Future

XX	

Supply Voltage[4]

3	3.3 Vdc
5	5.0 Vdc

Transfer Function

A	10 % to 90 % of Vsupply (analog), 2^{24} counts (digital)

Output Type

A	Analog	3	I²C, Address 0x38
S	SPI	4	I²C, Address 0x48
0	I²C, Address 0x08	5	I²C, Address 0x58
1	I²C, Address 0x18	6	I²C, Address 0x68
2	I²C, Address 0x28	7	I²C, Address 0x78

Pressure Range

12 bar to 20 bar		175 psi to 300 psi	
Absolute		Absolute	
012BA	12 bar	175PA	175psi
016BA	16 bar	230PA	230psi
020BA	20 bar	300PA	300psi
Guage		Guage	
012BG	12 bar	175PG	175psi
016BG	16 bar	230PG	230psi
020BG	20 bar	300PG	300psi

[1] Other configurations available on request.

[2] The specialized layer of shock-proof adhesive may be offered at pressure ranges below 12 bar where the application requires a more robust sensing solution.

[3] Customer needs to validate Honeywell sensors for liquid media before using in their specific application.

[4] Sensors are not reverse polarity protected. Incorrect application of supply voltage or ground to the wrong pin may cause electrical failure. Where not stated above, all other specifications remain the same as ABP2.

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES | HIGH PRESSURE, HIGH TEMPERATURE

TABLE 10. PRESSURE RANGE: 12 BAR TO 20 BAR FOR HIGH PRESSURE & HIGH TEMPERATURE SENSORS FOR 'T' & 'G'

Pressure Range	Pressure Range		Unit	Overpressure[1]	Burst Pressure[2]	Total Error Band[3] (% FSS)	Typical Offset Shift with Reflow (% FSS)	Long-term Stability (1000 HR) (% FSS)	Transfer Function for Digital Version
	$P_{Min.}$	$P_{Max.}$		Port 1 (P1)	Port 1 (P1)	0°C to 85°C			
Absolute									
012BA	0	12	bar	30	40	±1.5	±1.0	±0.2	A
016BA	0	16	bar	30	40	±1.5	±1.0	±0.2	A
020BA	0	20	bar	30	40	±1.5	±1.0	±0.2	A
Gage									
012BG	0	12	bar	30	40	±1.5	±1.0	±0.2	A
016BG	0	16	bar	30	40	±1.5	±1.0	±0.2	A
020BG	0	20	bar	30	40	±1.5	±1.0	±0.2	A
Absolute									
175PA	0	175	psi	440	600	±1.5	±1.0	±0.2	A
230PA	0	230	psi	440	600	±1.5	±1.0	±0.2	A
300PA	0	300	psi	440	600	±1.5	±1.0	±0.2	A
Gage									
175PG	0	175	psi	440	600	±1.5	±1.0	±0.2	A
230PG	0	230	psi	440	600	±1.5	±1.0	±0.2	A
300PG	0	300	psi	440	600	±1.5	±1.0	±0.2	A

[1]**Overpressure:** The maximum pressure which may safely be applied to the product for it to remain in specification once pressure is returned to the operating pressure range. Exposure to higher pressures may cause permanent damage to the product. Unless otherwise specified, this applies to all available pressure ports at any temperature within the operating temperature range.

[2]**Burst Pressure:** The maximum pressure that may be applied to any port of the product without causing escape of pressure media. The product should not be expected to function after exposure to any pressure beyond the burst pressure.

[3]**Total Error Band:** The maximum deviation from the ideal transfer function over the entire compensated temperature and pressure range without causing changes in specified performance.

Downloaded from Arrow.com.


BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

SELECT ABP2 SERIES SENSORS MOUNTED ON BREAKOUT BOARDS

Breakout boards, with or without the sensor premounted (see Figure 9 and Tables 11, 12, and 13) are designed for use with the Honeywell SEB Sensor Evaluation Kit.

Figure 9. APB2 Series Sensors and Breakout Boards

SN Leadless SMT sensor premounted on breakout board (ABP2LSNT060PGSA3BB)



Breakout board (ABP2-BREAKOUT-BRD)




TABLE 11. ORDER GUIDE FOR ABP2 SERIES SENSORS AND BREAKOUT BOARDS

Catalog Listing	Description
ABP2MRRN004ND2A3BB	ABP2 Series sensor with SMT package, plastic dual radial barbed ports, same side pressure port, dry gases only, no diagnostics, ±4 inH_2O differential pressure range, I^2C address 0x28, 10 % to 90 % of 2^{24} counts digital transfer function, 3.3 Vdc supply premounted on breakout board
ABP2MDAN004ND2A3BB	ABP2 Series sensor with SMT package, plastic dual axial barbed ports same side, dry gases only, no diagnostics, ±4 inH_2O differential pressure range, I^2C address 0x28, 10 % to 90 % of 2^{24} counts digital transfer function, 3.3 Vdc supply premounted on breakout board
ABP2MVNT400MG2A3BB	ABP2 Series sensor with leaded SMT package, metal single axial tapered pressure port, liquid media, food-grade silicone gel, no diagnostics, 400 mbar gage pressure range, I^2C address 0x28, 10 % to 90 % of 2^{24} counts digital transfer function, 3.3 Vdc supply premounted on breakout board
ABP2LANT001PG2A3BB	ABP2 Series sensor with leadless SMT package, plastic single axial barbed pressure port, liquid media, food-grade silicone gel, no diagnostics, 1 psi gage pressure range, I^2C address 0x28, 10 % to 90 % of 2^{24} counts digital transfer function, 3.3 Vdc supply premounted on breakout board
ABP2LSNT060PGSA3BB	ABP2 Series sensor with leadless SMT package, metal single axial straight barbless pressure port, liquid media, food-grade silicone gel, no diagnostics, 60 psi gage pressure range, SPI output type, 10 % to 90 % of 2^{24} counts digital transfer function, 3.3 Vdc supply premounted on breakout board
ABP2LANT001BA2A3BB	ABP2 Series sensor with leadless SMT package, plastic single axial barbed pressure port, liquid media, food-grade silicone gel, no diagnostics, 1 bar absolute pressure range, I^2C address 0x28, 10 % to 90 % of 2^{24} counts digital transfer function, 3.3 Vdc supply premounted on breakout board
ABP2-BREAKOUT-BRD	Bare breakout board for use with SMT and leadless SMT packages with AN, SN, VN, NN, RN, or RR pressure ports

Downloaded from Arrow.com.

SELECT ABP2 SERIES SENSORS MOUNTED ON BREAKOUT BOARDS (CONTINUED)

TABLE 12. BREAKOUT BOARD ASSEMBLY DETAILS

SL Number	REF Designator	Description	Manufacturer Part Number	Populate	Description
1	C1	Capacitor, ceramic, 0.1 µF, 16 V, X7R, 10 % SMD 0402	GCM155R71C104KA55J	Populated	A decoupling capacitor, breakout board shipped with this part assembled
2	C2	Capacitor, ceramic SMD 0402	NA	DNP	Do not populate
3	R1, R2	Resistor SMD 0402 SCL line/R1 and SDA line R2	NA	DNP	Optional pull-up resistors for I^2C output (not populated on the breakout board); recommended pull-up resistor value: 1 kOhm to 10 kOhm
4	R3	Resistor, SMD 0402	NA	DNP	Jumper resistor, do not populate
5	P1	Connector, header, 6 pin, straight, 2,54 mm pitch through hole	826629-6	Populated	6 pin connector
6	U1	ABP2 sensor	ABP2	Populated	Respective ABP2 sensor mounted

TABLE 13. BREAKOUT BOARD PINOUTS

Pin Number	I^2C Output	SPI Output
1	V_{DD}	V_{DD}
2	SCL	SCLK
3	EOC	MISO
4	SDA	MOSI
5	GND	GND
6	NC	SS

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

TABLE 14. PRESSURE RANGE SPECIFICATIONS: 6 MBAR TO 12 BAR FOR PRODUCT OPTIONS "N", "D", "T" AND "V" ONLY

Pressure Range	Pressure Range		Unit	Overpressure[1]		Burst Pressure[2]		Common Mode Pressure[3]	Total Error Band[4] (% FSS)			Typical Offset Shift with Reflow (% FSS)	Long-term Stability (1000 HR) (% FSS)	Transfer Function for Digital Versions
	$P_{Min.}$	$P_{Max.}$		Port 1 (P1)	Port 2 (P2)	Port 1 (P1)	Port 2 (P2)		0°C to 50°C	-20°C to 85°C	-40°C to 110°C			
Absolute														
001BA	0	1	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
1.6BA	0	1.6	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
2.5BA	0	2.5	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
Differential														
2.5MD	-2.5	2.5	mbar	340	340	1020	510	–	±2.5	–	–	±1.0	±0.3	A
006MD	-6	6	mbar	340	340	1020	510	–	±2.5	–	–	±1.0	±0.3	A
010MD	-10	10	mbar	340	340	1020	510	–	±2.5	–	–	±1.0	±0.3	A
016MD	-16	16	mbar	700	700	7000	1000	–	±2.0	±3.5	–	±1.0	±0.3	A
025MD	-25	25	mbar	700	700	7000	1000	–	±2.0	±3.5	–	±1.0	±0.3	A
040MD[5]	-40	40	mbar	2000	1000	7000	2000	2000	±1.5	±3.0	±4.5	NA	±0.2	A
060MD[5]	-60	60	mbar	2000	1000	7000	2000	2000	±1.5	±3.0	±4.5	NA	±0.2	A
100MD[5]	-100	100	mbar	2000	1000	7000	2000	2000	±1.5	±3.0	±4.5	NA	±0.2	A
160MD[5]	-160	160	mbar	2000	1000	7000	2000	2000	±1.5	±3.0	±4.5	NA	±0.2	A
250MD	-250	250	mbar	16000	–	25000	–	16000	±1.5	±3.0	±4.5	±1.0	±0.6	A
400MD	-400	400	mbar	16000	–	25000	–	16000	±1.5	±3.0	±4.5	±1.0	±0.6	A
600MD	-600	600	mbar	16000	–	25000	–	16000	±1.5	±3.0	±4.5	±1.0	±0.6	A
001BD	-1	1	bar	16	–	25	–	16	±1.5	±3.0	±4.5	±1.0	±0.2	A
1.6BD	-1.6	1.6	bar	16	–	25	–	16	±1.5	±3.0	±4.5	±1.0	±0.2	A
2.5BD	-2.5	2.5	bar	16	–	25	–	16	±1.5	±3.0	±4.5	±1.0	±0.2	A
004BD	-4	4	bar	16	–	25	–	16	±1.5	±3.0	±4.5	±1.0	±0.2	A
Gage														
006MG	0	6	mbar	340	-	1020	–	–	±2.5	–	–	±1.0	±0.3	A
010MG	0	10	mbar	340	–	1020	–	–	±2.5	–	–	±1.0	±0.3	A
016MG	0	16	mbar	340	–	1020	–	–	±2.5	–	–	±1.0	±0.3	A
025MG	0	25	mbar	700	–	7000	–	–	±2.0	±3.5	–	±1.0	±0.3	A
040MG	0	40	mbar	700	–	7000	–	–	±2.0	±3.5	–	±1.0	±0.3	A
060MG[5]	0	60	mbar	2000	–	7000	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
100MG[5]	0	100	mbar	2000	–	7000	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
160MG[5]	0	160	mbar	2000	–	7000	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
250MG[5]	0	250	mbar	2000	–	7000	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
400MG[5]	0	400	mbar	2000	–	7000	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
600MG	0	600	mbar	16000	–	25000	–	–	±1.5	±3.0	±4.5	±1.0	±0.6	A
001BG	0	1	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.5	A
1.6BG	0	1.6	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.3	A
2.5BG	0	2.5	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
004BG	0	4	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
006BG	0	6	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
008BG	0	8	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
010BG	0	10	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
012BG	0	12	bar	16	–	25	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A

[1] **Overpressure:** The maximum pressure which may safely be applied to the product for it to remain in specification once pressure is returned to the operating pressure range. Exposure to higher pressures may cause permanent damage to the product. Unless otherwise specified, this applies to all available pressure ports at any temperature within the operating temperature range.

[2] **Burst Pressure:** The maximum pressure that may be applied to any port of the product without causing escape of pressure media. The product should not be expected to function after exposure to any pressure beyond the burst pressure.

[3] **Common Mode Pressure:** The maximum pressure that can be applied simultaneously to both ports of a differential pressure sensor without causing changes in specified performance.

[4] **Total Error Band:** The maximum deviation from the ideal transfer function over the entire compensated temperature and pressure range without causing changes in specified performance.

[5] **Total Error Band** specified for these pressure ranges are after offset auto-zero correction post sensor reflow.

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

TABLE 15. PRESSURE RANGE SPECIFICATIONS: 250 MBAR TO 12 BAR FOR PRODUCT OPTIONS "G" AND "F" ONLY

Pressure Range	Pressure Range		Unit	Overpressure[1]		Burst Pressure[2]		Common Mode Pressure[3]	Total Error Band[4] (% FSS)			Typical Offset Shift with Reflow (% FSS)	Long-term Stability (1000 HR) (% FSS)	Transfer Function for Digital Versions
	$P_{Min.}$	$P_{Max.}$		Port 1 (P1)	Port 2 (P2)	Port 1 (P1)	Port 2 (P2)		0°C to 50°C	-20°C to 85°C	-40°C to 110°C			
Absolute														
001BA	0	1	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
1.6BA	0	1.6	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
2.5BA	0	2.5	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
004BA	0	4	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
006BA	0	6	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
008BA	0	8	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
010BA	0	10	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
012BA	0	12	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
Differential														
250MD	-250	250	mbar	16000	–	25000	–	16000	±2.0	±3.0	±4.5	±1.0	±0.5	A
400MD	-400	400	mbar	16000	–	25000	–	16000	±2.0	±3.0	±4.5	±1.0	±0.5	A
600MD	-600	600	mbar	16000	–	25000	–	16000	±2.0	±3.0	±4.5	±1.0	±0.5	A
001BD	-1	1	bar	16	–	25	–	16	±2.0	±3.0	±4.5	±1.0	±0.5	A
1.6BD	-1.6	1.6	bar	16	–	25	–	16	±2.0	±3.0	±4.5	±1.0	±0.5	A
2.5BD	-2.5	2.5	bar	16	–	25	–	16	±2.0	±3.0	±4.5	±1.0	±0.5	A
004BD	-4	4	bar	16	–	25	–	16	±2.0	±3.0	±4.5	±1.0	±0.5	A
Gage														
600MG	0	600	mbar	16000	–	25000	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
001BG	0	1	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
1.5BG	0	1.6	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
2.5BG	0	2.5	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
004BG	0	4	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
006BG	0	6	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
008BG	0	8	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
010BG	0	10	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
012BG	0	12	bar	16	–	25	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A

[1] **Overpressure:** The maximum pressure which may safely be applied to the product for it to remain in specification once pressure is returned to the operating pressure range. Exposure to higher pressures may cause permanent damage to the product. Unless otherwise specified, this applies to all available pressure ports at any temperature within the operating temperature range.

[2] **Burst Pressure:** The maximum pressure that may be applied to any port of the product without causing escape of pressure media. The product should not be expected to function after exposure to any pressure beyond the burst pressure.

[3] **Common Mode Pressure:** The maximum pressure that can be applied simultaneously to both ports of a differential pressure sensor without causing changes in specified performance.

[4] **Total Error Band:** The maximum deviation from the ideal transfer function over the entire compensated temperature and pressure range without causing changes in specified performance.

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

TABLE 16. PRESSURE RANGE SPECIFICATIONS: 600 PA TO 1.2 MPA FOR PRODUCT OPTIONS "N", "D", "T" AND "V" ONLY

Pressure Range	Pressure Range		Unit	Overpressure[1]		Burst Pressure[2]		Common Mode Pressure[3]	Total Error Band[4] (% FSS)			Typical Offset Shift with Reflow (% FSS)	Long-term Stability (1000 HR) (% FSS)	Transfer Function for Digital Versions
	$P_{Min.}$	$P_{Max.}$		Port 1 (P1)	Port 2 (P2)	Port 1 (P1)	Port 2 (P2)		0°C to 50°C	-20°C to 85°C	-40°C to 110°C			
Absolute														
100KA	0	100	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
160KA	0	160	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
250KA	0	250	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
Differential														
250LD	-250	250	Pa	34000	34000	100000	50000	–	±2.5	–	–	±1.0	±0.3	A
600LD	-600	600	Pa	34000	34000	100000	50000	–	±2.5	–	–	±1.0	±0.3	A
001KD	-1	1	kPa	34	34	100	50	–	±2.5	–	–	±1.0	±0.3	A
1.6KD	-1.6	1.6	kPa	70	70	700	100	–	±2.0	±3.5	–	±1.0	±0.3	A
2.5KD	-2.5	2.5	kPa	70	70	700	100	–	±2.0	±3.5	–	±1.0	±0.3	A
004KD[5]	-4	4	kPa	200	100	700	200	200	±1.5	±3.0	±4.5	NA	±0.2	A
006KD[5]	-6	6	kPa	200	100	700	200	200	±1.5	±3.0	±4.5	NA	±0.2	A
010KD[5]	-10	10	kPa	200	100	700	200	200	±1.5	±3.0	±4.5	NA	±0.2	A
016KD[5]	-16	16	kPa	200	100	700	200	200	±1.5	±3.0	±4.5	NA	±0.2	A
025KD	-25	25	kPa	1600	–	2500	–	16000	±1.5	±3.0	±4.5	±1.0	±0.6	A
040KD	-40	40	kPa	1600	–	2500	–	16000	±1.5	±3.0	±4.5	±1.0	±0.6	A
060KD	-60	60	kPa	1600	–	2500	–	16000	±1.5	±3.0	±4.5	±1.0	±0.6	A
100KD	-100	100	kPa	1600	–	2500	–	16000	±1.5	±3.0	±4.5	±1.0	±0.2	A
160KD	-160	160	kPa	1600	–	2500	–	16000	±1.5	±3.0	±4.5	±1.0	±0.2	A
250KD	-250	250	kPa	1600	–	2500	–	16000	±1.5	±3.0	±4.5	±1.0	±0.2	A
400KD	-400	400	kPa	1600	–	2500	–	16000	±1.5	±3.0	±4.5	±1.0	±0.2	A
Gage														
600LG	0	600	Pa	34000	–	100000	–	–	±2.5	–	–	±1.0	±0.3	A
001KG	0	1	kPa	34	–	100	–	–	±2.5	–	–	±1.0	±0.3	A
1.6KG	0	1.6	kPa	34	–	100	–	–	±2.5	–	–	±1.0	±0.3	A
2.5KG	0	2.5	kPa	70	–	700	–	–	±2.0	±3.5	–	±1.0	±0.3	A
004KG	0	4	kPa	70	–	700	–	–	±2.0	±3.5	–	±1.0	±0.3	A
006KG[5]	0	6	kPa	200	–	700	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
010KG[5]	0	10	kPa	200	–	700	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
016KG[5]	0	16	kPa	200	–	700	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
025KG[5]	0	25	kPa	200	–	700	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
040KG[5]	0	40	kPa	200	–	700	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
060KG	0	60	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.6	A
100KG	0	100	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.5	A
160KG	0	160	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
250KG	0	250	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
400KG	0	400	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
600KG	0	600	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
800KG	0	800	kPa	1600	–	2500	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
001GG	0	1	MPa	1.6	–	2.5	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
1.2GG	0	1.2	MPa	1.6	–	2.5	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A

[1] **Overpressure:** The maximum pressure which may safely be applied to the product for it to remain in specification once pressure is returned to the operating pressure range. Exposure to higher pressures may cause permanent damage to the product. Unless otherwise specified, this applies to all available pressure ports at any temperature within the operating temperature range.
[2] **Burst Pressure:** The maximum pressure that may be applied to any port of the product without causing escape of pressure media. The product should not be expected to function after exposure to any pressure beyond the burst pressure.
[3] **Common Mode Pressure:** The maximum pressure that can be applied simultaneously to both ports of a differential pressure sensor without causing changes in specified performance.
[4] **Total Error Band:** The maximum deviation from the ideal transfer function over the entire compensated temperature and pressure range without causing changes in specified performance.
[5] **Total Error Band** specified for these pressure ranges are after offset auto-zero correction post sensor reflow.

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

TABLE 17. PRESSURE RANGE SPECIFICATIONS: 25 KPA TO 1.2 MPA FOR PRODUCT OPTIONS "G" AND "F" ONLY

Pressure Range	Pressure Range		Unit	Overpressure[1]		Burst Pressure[2]		Common Mode Pressure[3]	Total Error Band[4] (% FSS)			Typical Offset Shift with Reflow (% FSS)	Long-term Stability (1000 HR) (% FSS)	Transfer Function for Digital Versions
	$P_{Min.}$	$P_{Max.}$		Port 1 (P1)	Port 2 (P2)	Port 1 (P1)	Port 2 (P2)		0°C to 50°C	-20°C to 85°C	-40°C to 110°C			
Absolute														
100KA	0	100	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
160KA	0	160	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
250KA	0	250	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
400KG	0	400	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
600KG	0	600	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
800KG	0	800	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
001GG	0	1	MPa	1.6	–	2.5	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
1.2GG	0	1.2	MPa	1.6	–	2.5	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
Differential														
025KD	-25	25	kPa	1600	–	2500	–	1600	±2.0	±3.0	±4.5	±1.0	±0.5	A
040KD	-40	40	kPa	1600	–	2500	–	1600	±2.0	±3.0	±4.5	±1.0	±0.5	A
060KD	-60	60	kPa	1600	–	2500	–	1600	±2.0	±3.0	±4.5	±1.0	±0.5	A
100KD	-100	100	kPa	1600	–	2500	–	1600	±2.0	±3.0	±4.5	±1.0	±0.5	A
160KD	-160	160	kPa	1600	–	2500	–	1600	±2.0	±3.0	±4.5	±1.0	±0.5	A
250KD	-250	250	kPa	1600	–	2500	–	1600	±2.0	±3.0	±4.5	±1.0	±0.5	A
400KD	-400	400	kPa	1600	–	2500	–	1600	±2.0	±3.0	±4.5	±1.0	±0.5	A
Gage														
060KG	0	60	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
100KG	0	100	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
160KG	0	160	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
250KG	0	250	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
400KG	0	400	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
600KG	0	600	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
800KG	0	800	kPa	1600	–	2500	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
001GG	0	1	MPa	1.6	–	2.5	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A
1.2GG	0	1.2	MPa	1.6	–	2.5	–	–	±2.0	±3.0	±4.5	±1.0	±0.5	A

[1] **Overpressure:** The maximum pressure which may safely be applied to the product for it to remain in specification once pressure is returned to the operating pressure range. Exposure to higher pressures may cause permanent damage to the product. Unless otherwise specified, this applies to all available pressure ports at any temperature within the operating temperature range.

[2] **Burst Pressure:** The maximum pressure that may be applied to any port of the product without causing escape of pressure media. The product should not be expected to function after exposure to any pressure beyond the burst pressure.

[3] **Common Mode Pressure:** The maximum pressure that can be applied simultaneously to both ports of a differential pressure sensor without causing changes in specified performance.

[4] **Total Error Band:** The maximum deviation from the ideal transfer function over the entire compensated temperature and pressure range without causing changes in specified performance.

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

TABLE 18. PRESSURE RANGE SPECIFICATIONS: 1PSI TO 175 PSI FOR PRODUCT OPTIONS "N","D","T" AND "V" ONLY
PRESSURE RANGE SPECIFICATIONS: 2 INH_20 TO 1 PSI FOR PRODUCT OPTIONS "N" AND "D" ONLY

Pressure Range	Pressure Range		Unit	Overpressure[1]		Burst Pressure[2]		Common Mode Pressure[3]	Total Error Band[4] (% FSS)			Typical Offset Shift with Reflow (% FSS)	Long-term Stability (1000 HR) (% FSS)	Transfer Function for Digital Versions
	$P_{Min.}$	$P_{Max.}$		Port 1 (P1)	Port 2 (P2)	Port 1 (P1)	Port 2 (P2)		0°C to 50°C	-20°C to 85°C	-40°C to 110°C			
Absolute														
015PA	0	15	psi	240	–	375	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
030PA	0	30	psi	240	–	375	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
Differential														
001ND	-1	1	inH_20	135	135	410	205	–	±2.5	–	–	±1.0	±0.3	A
002ND	-2	2	inH_20	135	135	410	205	–	±2.5	–	–	±1.0	±0.3	A
004ND	-4	4	inH_20	135	135	410	205	–	±2.5	–	–	±1.0	±0.3	A
005ND	-5	5	inH_20	270	270	2800	415	–	±2.0	±3.5	–	±1.0	±0.3	A
010ND	-10	10	inH_20	270	270	2800	415	–	±2.0	±3.5	–	±1.0	±0.3	A
020ND[5]	-20	20	inH_20	830	415	2800	830	830	±1.5	±3.0	±4.5	NA	±0.2	A
030ND[5]	-30	30	inH_20	830	415	2800	830	830	±1.5	±3.0	±4.5	NA	±0.2	A
001PD[5]	-1	1	psi	30	15	100	30	30	±1.5	±3.0	±4.5	NA	±0.2	A
005PD	-5	5	psi	240	–	375	–	240	±1.5	±3.0	±4.5	±1.0	±0.6	A
015PD	-15	15	psi	240	–	375	–	240	±1.5	±3.0	±4.5	±1.0	±0.2	A
030PD	-30	30	psi	240	–	375	–	240	±2.0	±3.0	±4.5	±1.0	±0.2	A
060PD	-60	60	psi	240	–	375	–	240	±2.0	±3.0	±4.5	±1.0	±0.2	A
Gage														
002NG	0	2	inH_20	135	–	410	–	–	±2.5	–	–	±1.0	±0.3	A
004NG	0	4	inH_20	135	–	410	–	–	±2.5	–	–	±1.0	±0.3	A
005NG	0	5	inH_20	135	–	410	–	–	±2.5	–	–	±1.0	±0.3	A
010NG	0	10	inH_20	270	–	2800	–	–	±2.0	±3.5	–	±1.0	±0.3	A
020NG	0	20	inH_20	270	–	2800	–	–	±2.0	±3.5	–	±1.0	±0.3	A
030NG[5]	0	30	inH_20	830	–	2800	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
001PG[5]	0	1	psi	30	–	100	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
005PG[5]	0	5	psi	30	–	100	–	–	±1.5	±3.0	±4.5	NA	±0.2	A
015PG	0	15	psi	240	–	375	–	–	±1.5	±3.0	±4.5	±1.0	±0.5	A
030PG	0	30	psi	240	–	375	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
060PG	0	60	psi	240	–	375	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
100PG	0	100	psi	240	–	375	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
150PG	0	150	psi	240	–	375	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A
175PG	0	175	psi	240	–	375	–	–	±1.5	±3.0	±4.5	±1.0	±0.2	A

[1] **Overpressure:** The maximum pressure which may safely be applied to the product for it to remain in specification once pressure is returned to the operating pressure range. Exposure to higher pressures may cause permanent damage to the product. Unless otherwise specified, this applies to all available pressure ports at any temperature within the operating temperature range.

[2] **Burst Pressure:** The maximum pressure that may be applied to any port of the product without causing escape of pressure media. The product should not be expected to function after exposure to any pressure beyond the burst pressure.

[3] **Common Mode Pressure:** The maximum pressure that can be applied simultaneously to both ports of a differential pressure sensor without causing changes in specified performance.

[4] **Total Error Band:** The maximum deviation from the ideal transfer function over the entire compensated temperature and pressure range without causing changes in specified performance.

[5] **Total Error Band** specified for these pressure ranges are after offset auto-zero correction post sensor reflow.

Downloaded from Arrow.com.

BASIC BOARD-MOUNT PRESSURE SENSORS
ABP2 SERIES

TABLE 19. PRESSURE RANGE SPECIFICATIONS: 5 PSI TO 175 PSI FOR PRODUCT OPTIONS "G" AND "F" ONLY

Pressure Range	Pressure Range		Unit	Overpressure[1]		Burst Pressure[2]		Common Mode Pressure[3]	Total Error Band[4] (% FSS)			Typical Offset Shift with Reflow (% FSS)	Long-term Stability (1000 HR) (% FSS)	Transfer Function for Digital Versions
	$P_{Min.}$	$P_{Max.}$		Port 1 (P1)	Port 2 (P2)	Port 1 (P1)	Port 2 (P2)		0°C to 50°C	-20°C to 85°C	-40°C to 110°C			
Absolute														
015PA	0	15	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
030PA	0	30	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
060PA	0	60	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
100PA	0	100	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
150PA	0	150	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
175PA	0	175	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
Differential														
005PD	-5	5	psi	240	—	375	—	240	±2.0	±3.0	±4.5	±1.0	±0.5	A
015PD	-15	15	psi	240	—	375	—	240	±2.0	±3.0	±4.5	±1.0	±0.5	A
030PD	-30	30	psi	240	—	375	—	240	±2.0	±3.0	±4.5	±1.0	±0.5	A
060PD	-60	60	psi	240	—	375	—	240	±2.0	±3.0	±4.5	±1.0	±0.5	A
Gage														
015PG	0	15	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
030PG	0	30	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
060PG	0	60	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
100PG	0	100	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
150PG	0	150	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A
175PG	0	175	psi	240	—	375	—	—	±2.0	±3.0	±4.5	±1.0	±0.5	A

[1] **Overpressure:** The maximum pressure which may safely be applied to the product for it to remain in specification once pressure is returned to the operating pressure range. Exposure to higher pressures may cause permanent damage to the product. Unless otherwise specified, this applies to all available pressure ports at any temperature within the operating temperature range.

[2] **Burst Pressure:** The maximum pressure that may be applied to any port of the product without causing escape of pressure media. The product should not be expected to function after exposure to any pressure beyond the burst pressure.

[3] **Common Mode Pressure:** The maximum pressure that can be applied simultaneously to both ports of a differential pressure sensor without causing changes in specified performance.


[4] **Total Error Band:** The maximum deviation from the ideal transfer function over the entire compensated temperature and pressure range without causing changes in specified performance.


Downloaded from Arrow.com.

DIMENSIONAL DRAWINGS


Figure 10. DIP Package Dimensional Drawings (For reference only: mm [in].)


DIP NN: Plastic no port





DIP AN: Plastic single axial barbed port







Downloaded from Arrow.com.


Figure 10. DIP Package Dimensional Drawings (Continued)


DIP VN: Metal single axial barbless port





DIP SN: Metal single axial straight barbless port







Downloaded from Arrow.com.


Figure 10. DIP Package Dimensional Drawings (Continued)


DIP RN: Plastic single radial barbed port







DIP RR: Plastic dual radial barbed ports, same side





DIP DA: Plastic dual axial barbed ports, same side







Downloaded from Arrow.com.


Figure 11. SMT Package Dimensional Drawings (For reference only: mm [in].)


SMT NN: Plastic no port







SMT AN: Plastic single axial barbed port







SMT VN: Metal single axial barbless port





SMT SN: Metal single axial straight barbless port







Downloaded from Arrow.com.

Figure 11. SMT Package Dimensional Drawings (Continued)


SMT RN: Plastic single radial barbed port



SMT RR: Plastic dual radial barbed ports, same side




SMT DA: Plastic dual axial barbed ports, same side




Downloaded from Arrow.com.

Figure 12. Leadless SMT Package Dimensional Drawings (For Reference Only: mm [in].)


Leadless SMT NN: Plastic no port






Leadless SMT AN: Plastic single axial barbed port






Leadless SMT VN: Metal single axial barbless port





Leadless SMT SN: Metal single axial straight port








Downloaded from Arrow.com.


Figure 12. Leadless SMT Package Dimensional Drawings (For Reference Only: mm [in].)

Leadless SMT NX: Plastic no port












Leadless SMT VX: Metal single axial barbless port













Leadless SMT SX: Metal single axial straight port












Downloaded from Arrow.com.


Figure 12. DIP Package Dimensional Drawings (For Reference Only: mm [in].)

DIP NX: Plastic no port













DIP VX: Metal single axial barbless port













DIP SX: Metal single axial straight port










Downloaded from Arrow.com.


Figure 12. SMT Package Dimensional Drawings (For Reference Only: mm [in].)


SMT NX: Plastic no port







SMT VX: Metal single axial barbless port





SMT SX: Metal single axial straight port






Downloaded from Arrow.com.

TABLE 20. PINOUT


Output Type	Pin 1	Pin 2	Pin 3	Pin 4	Pin 5	Pin 6
I²C	GND	V_{DD}	EOC	NC	SDA	SCL
SPI	GND	V_{DD}	MISO	SS	MOSI	SCLK
Analog	GND	NC	V_{OUT}	NC	NC	V_{DD}

Figure 13. Recommended PCB Layout and Part Marketing Details


DIP Packages
All pressure port styles except DA




SMT Packages
All pressure port styles except DA




Leadless SMT Packages
All pressure port styles




DIP Packages
Pressure port style DA only




DMT Packages
Pressure port style DA only



Leadless SMT Packages
Hight Pressure, High Temperature
NX, VX, SX port styles



Part Marking Details



CATALOG LISTING: XXXXXXXXX'
EXAMPLE: N010BAA3
N = DRY GASES ONLY NO DIAGNOSTICS, 010B = 10 bar, A = ABSOLUTE, A = ANALOG, A = 10 % to 90 % of 2^24 COUNTS (DIGITAL). 3 to 3.3 Vdc
DATE CODE: YMDD-LLN
EXAMPLE: 4921-LLN, 4 = 2024, 9 = SEP, 21 = 21ST

Downloaded from Arrow.com.

1.0 GENERAL INFORMATION

Please see Figures 7, 8, and 9 for product dimensions and pinout details.

2.0 PINOUT AND FUNCTIONALITY

TABLE 21. PINOUT AND FUNCTIONALITY

Pad Number	I²C Sensor		SPI Sensor	
	Name	Description	Name	Description
1	GND	Ground reference voltage signal	GND	Ground reference voltage signal
2	V_{DD}	Positive supply voltage	V_{DD}	Positive supply voltage
3	EOC[1]	End-of-conversion indicator: This pin is set high when a measurement and calculation have been completed and the data is ready to be clocked out	MISO	Master In/Sensor Out: Data output
4	NC	No connection	SS	Sensor Select: Chip select
5	SDA	Data in/out	MOSI	Master Out/Sensor In: Data in
6	SCL	Clock input	SCLK	Clock input

[1] For more details on EOC functionality, please refer to the technical note.

3.0 START-UP TIMING

On power-up, the ABP2 Series digital sensor is able to receive the first command after 2.5 ms from when the V_{DD} supply is within operating specifications.

4.0 POWER SUPPLY REQUIREMENT

Verify that system power to the sensor meets the V_{DD} rising slope requirement (minimum V_{DD} rising slope is at least 10 V/ms).

Downloaded from Arrow.com.

5.0 REFERENCE CIRCUIT DESIGNS

5.1 DIGITAL OUTPUT VERSIONS

Figure 14. I²C SPI Circuit Diagram






Figure 15. SPI Circuit Diagram



5.2 ANALOG OUPUT VERSIONS

Figure 16. Analog Circuit Diagram



5.3 BYPASS CAPACITOR USE

NOTICE

To ensure output noise suppression, place an external bypass capacitor of 0.1 µF very close to the sensor power supply pin (see Figures 14 and 15) in the end-user design.

Downloaded from Arrow.com.

6.0 I²C COMMUNICATIONS


6.1 I²C BUS CONFIGURATION (SEE FIGURE 17.)

The I²C bus is a simple, serial 8-bit oriented computer bus for efficient I²C (Inter-IC) control. It provides good support for communication between different ICs across short circuit-board distances, such as interfacing microcontrollers with various low speed peripheral devices. For detailed specifications of the I²C protocol, see Version 6 (April 2014) of the I²C Bus Specification (source: NXP Semiconductor at https://www.nxp.com/docs/en/user-guide/UM10204.pdf).

Each device connected to the bus is software addressable by a unique address and a simple Master/Sensor relationship that exists at all times. The output stages of devices connected to the bus are designed around an open collector architecture. Because of this, pull-up resistors to $+V_{DD}$ must be provided on the bus. Both SDA and SCL are bidirectional lines, and it is important to system performance to match the capacitive loads on both lines. In addition, in accordance with the I²C specification, the maximum allowable capacitance on either line is 400 pF to ensure reliable edge transitions at 400 kHz clock speeds.

When the bus is free, both lines are pulled up to $+V_{DD}$. Data on the I²C bus can be transferred at a rate up to 100 kbit/s in the standard-mode, or up to 400 kbit/s in the fast-mode.

Figure 17. I²C Bus Configuration



6.2 I²C DATA TRANSFER

The ABP2 Series I²C sensors are designed to respond to requests from a Master device. Following the address and read bit from the Master, the ABP2 Series digital output pressure sensors are designed to output up to 7 bytes of data. The first data byte is the Status Byte (8 bit), the second to fourth bytes are the compensated pressure output (24 bit) and the fifth to seventh bytes are the compensated temperature output (24 bit).

6.3 I²C SENSOR ADDRESS

Each ABP2 Series I²C sensor is referenced on the bus by a 7-bit Sensor address. The default address for the ABP2 Series is 40 (28 hex). Other available standard addresses are: 08 (08 hex), 24 (18 hex), 56 (38 hex), 72 (48 hex), 88 (58 hex), 104 (68 hex), 120 (78 hex). (Other custom values are available. Please contact Honeywell Customer Service with questions regarding custom Sensor addresses.)

6.4 I²C PRESSURE AND TEMPERATURE READING

To read out the compensated pressure and temperature reading, the Master generates a START condition and sends the Sensor address followed by a read bit (1). After the Sensor generates an acknowledge, it will transmit up to 7 bytes of data. The first data byte is the Status Byte (8-bit) and the second to fourth bytes are the compensated pressure output (24 bit) and the fifth to seventh bytes are the compensated temperature output (24 bit). The Master must acknowledge the receipt of each byte, and can terminate the communication by sending a Not Acknowledge (NACK) bit followed by a Stop bit after receiving the required bytes of data.

Downloaded from Arrow.com.

6.5 I²C STATUS BYTE

TABLE 22. I²C STATUS BYTE EXPLANATION






BIT (Meaning)	Status	Comment
7	Always 0	—
6 (Power indication)	1 = device is powered 0 = device is not powered	—
5 (Busy flag)	1 = device is busy	Indicates that the data for the last command is not yet available. No new commands are processed if the device is busy.
4	Always 0	—
3	Always 0	—
2 (Memory integrity/error flag)	0 = integrity test passed 1 = integrity test failed	Indicates whether the checksum-based integrity check passed or failed; the memory error status bit is calculated only during the power-up sequence.
1	Always 0	—
0 (Math saturation)	1 = internal math saturation has occurred	—

6.6 I²C COMMUNICATIONS

6.6.1 I²C OUTPUT MEASUREMENT COMMAND

To communicate with the ABP2 Series I²C output sensor using an Output Measurement Command of "0xAA", followed by "0x00" "0x00", follow the steps shown in Table 23. This command will cause the device to exit Standby Mode and enter Operating Mode. At the conclusion of the measurement cycle, the device will automatically re-enter Standby Mode.

TABLE 23. I²C OUTPUT MEASUREMENT COMMAND






Step	Action	Notes
1		
2	**Option 1:** Wait until the busy flag in the Status Byte clears.  **Option 2:** Wait for at least 5 ms for the data conversion to occur. **Option 3:** Wait for the EOC indicator.	
3	To read only the 24-bit pressure output along with the 8-bit Status Byte:t  To read the 24-bit pressure output and 24-bit temperature output along with the 8-bit Status Byte: 	

Downloaded from Arrow.com.

6.6.2 I²C SENSOR ADDRESS OF 0X28


To communicate with the ABP2 Series I²C output sensor with an I²C Sensor Address of 0x28 (hex), follow the steps shown in Table 24.

TABLE 24. I²C SENSOR ADDRESS OF 0X28 COMMUNICATIONS

Step	Action	Notes
1		
2	**Option 1:** Wait until the busy flag in the Status Byte clears.  **Option 2:** Wait for at least 5 ms for the data conversion to occur. **Option 3:** Wait for the EOC indicator.	
3	To read the 24-bit pressure output along with the 8-bit Status Byte:  To read the 24-bit pressure output and the 24-bit temperature output along with the 8-bit Status Byte: 	

6.7 I²C TIMING AND LEVEL PARAMETERS

TABLE 25. I²C BUS TIMING DIAGRAM AND PARAMETERS



Characteristic	Abbreviation	Min.	Typ.	Max.	Unit
SCL clock frequency	f_{SCL}	100	–	400	kHz
Start condition hold time relative to SCL edge	t_{HDSTA}	0.1	–	–	µs
Minimum SCL clock low width[1]	t_{LOW}	0.6	–	–	µs
Minimum SCL clock high width[1]	t_{HIGH}	0.6	–	–	µs
Start condition setup time relative to SCL edge	t_{SUSTA}	0.1	–	–	µs
Data hold time on SDA relative to SCL edge	t_{HDDAT}	0	–	–	µs
Data setup time on SDA relative to SCL edge	t_{SUDAT}	0.1	–	–	µs
Stop condition setup time on SCL	t_{SUSTO}	0.1	–	–	µs
Bus free time between stop condition and start condition	t_{BUS}	2	–	–	µs
Output level low	Out_{low}	–	0	0.2	V_{DD}
Output level high	Out_{high}	0.8	1	–	V_{DD}
Pull-up resistance on SDA and SCL	R_p	1	–	50	kOhm

[1] Combined low and high widths must equal or exceed minimum SCL period.

Downloaded from Arrow.com.

6.8 REFERENCE CODE (ARDUINO/GENUINO UNO) FOR I²C INTERFACE

See also Section 8.0 for details and examples of ABP2 Series Pressure and Temperature output calculations.

```
#include<Arduino.h>
#include<Wire.h>

uint8_t id = 0x28; // i2c address
uint8_t data[7]; // holds output data
uint8_t cmd[3] = {0xAA, 0x00, 0x00}; // command to be sent
double press_counts = 0; // digital pressure reading [counts]
double temp_counts = 0; // digital temperature reading [counts]
double pressure = 0; // pressure reading [bar, psi, kPa, etc.]
double temperature = 0; // temperature reading in deg C
double outputmax = 15099494; // output at maximum pressure [counts]
double outputmin = 1677722; // output at minimum pressure [counts]
double pmax = 1; // maximum value of pressure range [bar, psi, kPa, etc.]
double pmin = 0; // minimum value of pressure range [bar, psi, kPa, etc.]
double percentage = 0; // holds percentage of full scale data
char printBuffer[200], cBuff[20], percBuff[20], pBuff[20], tBuff[20];
void setup() {
  Serial.begin(9600);
  while (!Serial) {
    delay(10);
  }
  Wire.begin();
  sprintf(printBuffer, "\nStatus Register, 24 - bit Sensor data, Digital Pressure Counts,\
          Percentage of full scale pressure, Pressure Output, Temperature\n");
  Serial.println(printBuffer);
}
void loop() {
  Wire.beginTransmission(id);
  int stat = Wire.write (cmd, 3); // write command to the sensor
  stat |= Wire.endTransmission();
  delay(10);
  Wire.requestFrom(id, 7); // read back Sensor data 7 bytes
  int i = 0;
  for (i = 0; i < 7; i++) {
    data [i] = Wire.read();
  }
  press_counts = (double)((int32_t)data[3]+(int32_t)data[2]*(int32_t)256+
  (int32_t)data[1]*(int32_t)65536); // calculate digital pressure counts
  temp_counts = (double)((int32_t)data[6]+(int32_t)data[5]*(int32_t)256+
  (int32_t)data[4]*(int32_t)65536); // calculate digital temperature counts
  temperature = (temp_counts * 200 / 16777215) - 50; // calculate temperature in deg c
  percentage = (press_counts / 16777215) * 100; // calculate pressure as percentage of full scale
  //calculation of pressure value according to equation 2 of datasheet
  pressure = ((press_counts - outputmin) * (pmax - pmin)) / (outputmax - outputmin) + pmin;
  dtostrf(press_counts, 4, 1, cBuff);
  dtostrf(percentage, 4, 3, percBuff);
  dtostrf(pressure, 4, 3, pBuff);
  dtostrf(temperature, 4, 3, tBuff);
  /*
    The below code prints the raw data as well as the processed data
    Data format : Status Register, 24-bit Sensor Data, Digital Counts, percentage of full scale
pressure,
    pressure output, temperature
  */
  sprintf(printBuffer, " % x\t % 2x % 2x % 2x\t % s\t % s\t % s\t % s \n", data[0], data[1], data[2],
          data[3],
          cBuff, percBuff, pBuff, tBuff);
  Serial.print(printBuffer);
  delay(10);
}
```



Downloaded from Arrow.com.

7.0 SPI COMMUNICATIONS

7.1 SPI DEFINITION

The Serial Peripheral Interface (SPI) is a simple bus system for synchronous serial communication between one Master and one or more Sensors. It operates either in full-duplex or half-duplex mode, allowing communication to occur in either both directions simultaneously, or in one direction only. The Master device initiates an information transfer on the bus and generates clock and control signals. Sensor devices are controlled by the Master through individual Sensors Select (SS) lines and are active only when selected. The ABP2 Series SPI sensors operate in full-duplex mode only, with data transfer from the Sensors to the Master. This data transmission uses four, unidirectional bus lines. The Master controls SCLK, MOSI and SS; the Sensor controls MISO. (See Figure 18.)

Figure 18. SPI Bus Configuration




IMPORTANT:

If more than one ABP2 sensor, or other SPI slave devices, or more than one Master, are connected to the same SPI bus, before very first transaction on the SPI bus, bring SS line of each ABP2 sensor from High state to Low state, hold the Low state for minimum of 200 us, and release it to High state.

7.2 SPI DATA TRANSFER

Communicate with the ABP2 Series SPI sensors by de-asserting the Sensor Select (SS) line. At this point, the sensor is no longer idle, and will begin sending data once a clock is received. ABP2 Series SPI sensors are configured for SPI operation in mode 0 (clock polarity is 0 and clock phase is 0). (See Figure 19.)

Figure 19. Example of 1 Byte SPI Data Transfer



Once the clocking begins, the ABP2 Series SPI sensor is designed to output up to 7 bytes of data. The first data byte is the Status Byte (8-bit), the second to fourth bytes are the compensated pressure output (24-bit) and the fifth to seventh bytes are the compensated temperature output (24-bit).

Downloaded from Arrow.com.

7.3 SPI PRESSURE AND TEMPERATURE READING

To read out the compensated pressure and temperature reading, the Master generates the necessary clock signal after activating the sensor with the Sensor Select (SS) line. The sensor will transmit up to 7 bytes of data. The first data byte is the Status Byte (8-bit), the second to fourth bytes are the compensated pressure output (24-bit) and the fifth to seventh bytes are the compensated temperature output (24-bit). The Master can terminate the communication by stopping the clock and deactivating the SS line.

7.4 SPI STATUS BYTE

The SPI status byte contains the bits shown in Table 26.

TABLE 26. SPI STATUS BYTE EXPLANATION

Bit (Meaning)	Status	Comment
7	Always 0	—
6 (Power indication)	1 = device is powered 0 = device is not powered	—
5 (Busy flag)	1 = device is busy	Indicates that the data for the last command is not yet available. No new commands are processed if the device is busy.
4	Always 0	—
3	Always 0	—
2 (Memory integrity/error flag)	0 = integrity test passed 1 = integrity test failed	Indicates whether the checksum-based integrity check passed or failed; the memory error status bit is calculated only during the power-up sequence.
1	Always 0	—
0 (Math saturation)	1 = internal math saturation has occurred	—

Downloaded from Arrow.com.

7.5 SPI COMMUNICATION

To communicate with the ABP2 Series SPI output sensor using an Output Measurement Command of "0xAA", followed by "0x00" "0x00", follow the steps shown in Table 27. This command will cause the device to exit Standby Mode and enter Operating Mode. At the conclusion of the measurement cycle, the device will automatically re-enter Standby Mode.


TABLE 27. SPI OUTPUT MEASUREMENT COMMAND

Step	Action	Notes
1	The data on MISO depend on the preceding command. Discard the data on the MISO line. MOSI: 0xAA | 0x00 | 0x00 — Measurement Command | CmdData <15:8> | CmdData <7:0> MISO: Status | Data | Data	Master to Sensor Sensor to Master • NOP Command is "0xF0".
2	**Option 1:** Wait until the busy flag in the Status Byte clears. MOSI: 0xF0 — Command = NOP MISO: Status **Option 2:** Wait for at least 5 ms for the data conversion to occur.	
3	To read only the 24-bit pressure output along with the 8-bit Status Byte: MOSI: 0xF0 | 0x00 | 0x00 | 0x00 — Command = NOP | 00_{Hex} | 00_{Hex} | 00_{Hex} MISO: Status | PressData <24:16> | PressData <15:8> | PressData <7:0> To read the 24-bit pressure output and the 24-bit temperature output along with the 8-bit Status Byte: MOSI: 0xF0 | 0x00 | 0x00 | 0x00 | 0x00 | 0x00 | 0x00 — Command = NOP | 00_{Hex} | 00_{Hex} | 00_{Hex} | 00_{Hex} | 00_{Hex} | 00_{Hex} MISO: Status | PressData <24:16> | PressData <15:8> | PressData <7:0> | TempData <24:16> | TempData <15:8> | TempData <7:0>	

Downloaded from Arrow.com.

7.6 SPI TIMING AND LEVEL PARAMETERS

TABLE 28. SPI BUS TIMING DIAGRAM AND PARAMETERS



Characteristic	Abbreviation	Min.	Typ.	Max.	Unit
SCLK clock frequency	f_{SCLK}	50	—	800	kHz
SS drop to first clock edge	t_{HDSS}	2.5	—	—	µs
Minimum SCLK clock low width[1]	t_{LOW}	0.6	—	—	µs
Minimum SCLK clock high width[1]	t_{HIGH}	0.6	—	—	µs
Clock edge to data transition	t_{CLKD}	0	—	—	µs
Rise of SS relative to last clock edge	t_{SUSS}	0.1	—	—	µs
Bus free time between rise and fall of SS	t_{BUS}	2	—	—	µs
Output level low	Out_{low}	—	0	0.2	V_{DD}
Output level high	Out_{high}	0.8	1	—	V_{DD}

[1]Combined low and high widths must equal or exceed minimum SCLK period.

Downloaded from Arrow.com.

7.7 REFERENCE CODE (ARDUINO/GENUINO UNO) FOR SPI INTERFACE

See also Section 8.0 for details and examples of ABP2 Series Pressure and Temperature output calculations.

```
#include<Arduino.h>
#include<SPI.h>

double press_counts = 0; // digital pressure reading [counts]
double temp_counts = 0; // digital temperature reading [counts]
double pressure = 0; // pressure reading [bar, psi, kPa, etc.]
double temperature = 0; // temperature reading in deg C
double outputmax = 15099494; // output at maximum pressure [counts]
double outputmin = 1677722; // output at minimum pressure [counts]
double pmax = 1; // maximum value of pressure range [bar, psi, kPa, etc.]
double pmin = 0; // minimum value of pressure range [bar, psi, kPa, etc.]
double percentage = 0; // holds percentage of full scale data
char printBuffer[200], cBuff[20], percBuff[20], pBuff[20], tBuff[20];
void setup() {
  Serial.begin(9600);
  while (!Serial) {
    delay(10);
  }
  sprintf(printBuffer, "\nStatus Register, 24-bit Sensor data, Digital Pressure Counts,\
  Percentage of full scale pressure,Pressure Output, Temperature\n");
  Serial.println(printBuffer);
  SPI.begin();
  pinMode(10, OUTPUT); // pin 10 as SS
  digitalWrite(10, HIGH); // set SS High
}
void loop() {
  delay(1);
  while (1) {
    uint8_t data[7] = {0xF0, 0x00, 0x00, 0x00, 0x00, 0x00, 0x00}; // holds output data
    uint8_t cmd[3] = {0xAA, 0x00, 0x00}; // command to be sent
    SPI.beginTransaction(SPISettings(200000, MSBFIRST, SPI_MODE0)); //SPI at 200kHz
    digitalWrite(10, LOW); // set SS Low
    SPI.transfer(cmd, 3); // send Read Command
    digitalWrite(10, HIGH); // set SS High
    delay(10); // wait for conversion
    digitalWrite(10, LOW);
    SPI.transfer(data, 7);
    digitalWrite(10, HIGH);
    SPI.endTransaction();
    press_counts = (double)((int32_t)data[3]+(int32_t)data[2]*(int32_t)256+
    (int32_t)data[1]*(int32_t)65536); // calculate digital pressure counts
    temp_counts = (double)((int32_t)data[6]+(int32_t)data[5]*(int32_t)256+
    (int32_t)data[4]*(int32_t)65536); // calculate digital temperature counts
    temperature = (temp_counts * 200 / 16777215) - 50; // calculate temperature in deg c
    percentage = (press_counts / 16777215) * 100; // calculate pressure as percentage of full scale
    //calculation of pressure value according to equation 2 of datasheet
    pressure = ((press_counts - outputmin) * (pmax - pmin)) / (outputmax - outputmin) + pmin;
    dtostrf(press_counts, 4, 1, cBuff);
    dtostrf(percentage, 4, 3, percBuff);
    dtostrf(pressure, 4, 3, pBuff);
    dtostrf(temperature, 4, 3, tBuff);
    /*
      The below code prints the raw data as well as the processed data
      Data format : Status Register, 24-bit Sensor Data, Digital Counts, percentage of full scale pressure,
pressure output,
      temperature
    */
    sprintf(printBuffer, "%x\t%2x %2x %2x\t%s\t%s\t%s\t%s \n", data[0], data[1], data[2], data[3],
            cBuff, percBuff, pBuff, tBuff);
    Serial.print(printBuffer);
    delay(10);
  }
}
```


Downloaded from Arrow.com.

8.0 ABP2 SERIES CALCULATIONS

8.1 DIGITAL OUTPUT VERSIONS

8.1.1 Pressure Output

The ABP2 Series sensor pressure output may be expressed by the transfer function of the device as shown in Equation 1:

Equation 1: Pressure Sensor Transfer Function

$$\text{Output} = \frac{\text{Output}_{max.} - \text{Output}_{min.}}{P_{max.} - P_{min.}} * (\text{Pressure} - P_{min.}) + \text{Output}_{min.}$$

Rearranging this equation to solve for Pressure provides Equation 2:

Equation 2: Pressure Output Function

$$\text{Pressure} = \frac{(\text{Output} - \text{Output}_{min.}) * (P_{max.} - P_{min.})}{\text{Output}_{max.} - \text{Output}_{min.}} + P_{min.}$$

Where:

$\text{Output}_{max.}$ = output at maximum pressure [counts]
$\text{Output}_{min.}$ = output at minimum pressure [counts]
$P_{max.}$ = maximum value of pressure range [bar, psi, kPa, etc.]
$P_{min.}$ = minimum value of pressure range [bar, psi, kPa, etc.]
Pressure = pressure reading [bar, psi, kPa, etc.]
Output = digital pressure reading [counts]

Example: Calculate the pressure for a -1 psi to 1 psi gage sensor with a 10 to 90 calibration, and a pressure output of 14260634 (decimal) counts:

$\text{Output}_{max.}$ = 15099494 counts (90 of 2^{24} counts or 0xE66666)
$\text{Output}_{min.}$ = 1677722 counts (10 of 2^{24} counts or 0x19999A)
$P_{max.}$ = 1 psi
$P_{min.}$ = -1 psi
Pressure = calculated pressure in psi
Output = 14260634 counts

$$\text{Pressure} = \left(\frac{(14260634 - 1677722) \times (1 - (-1))}{15099494 - 1677722}\right) + (-1)$$

$$\text{Pressure} = \left(\frac{25165824}{13421772}\right) + (-1)$$

$$\text{Pressure} = 0.875 \text{ psi}$$

Downloaded from Arrow.com.

8.1.2 Temperature Output

The ABP2 Series sensor temperature output may be expressed by the transfer function of the device as shown in Equation 3:

Equation 3: Temperature Output Transfer Function

$$\text{Temperature} = \frac{T_{out} * (T_{max.} - T_{min.})}{(2^{(24)} - 1)} + T_{min.}$$

Where:

Temperature = calculated temperature output in °C

T_{out} = digital temperature output in counts (decimal)

$T_{max.}$ = 150°C

$T_{min.}$ = -50°C

Example: Calculate the temperature for a temperature output of 6291456 (decimal) counts.

$$\text{Temperature} = \frac{T_{out} * (150 - (-50))}{(2^{(24)} - 1)} + T_{min.}$$

$$\text{Temperature} = \frac{6291456 * 200}{16777215} - 50$$

$$\text{Temperature} = 25°C$$

Downloaded from Arrow.com.

8.2 ANALOG OUTPUT VERSIONS

The ABP2 Series sensor temperature output may be expressed by the transfer function of the device as shown in Equation 1:

Equation 1: Pressure Output Transfer Function

$$\text{Output} = \frac{\text{Output}_{max.} - \text{Output}_{min.}}{P_{max.} - P_{min.}} * (\text{Pressure} - P_{min.}) + \text{Output}_{min.}$$

$$\text{Pressure} = \frac{(\text{Output} - \text{Output}_{min.}) * (P_{max.} - P_{min.})}{\text{Output}_{max.} - \text{Output}_{min.}} + P_{min.}$$

Where:

$\text{Output}_{max.}$ = output at maximum pressure [Vdc]
$\text{Output}_{min.}$ = output at minimum pressure [Vdc]
$P_{max.}$ = maximum value of pressure range [bar, psi, kPa, etc.]
$P_{min.}$ = minimum value of pressure range [bar, psi, kPa, etc.]
Pressure = pressure reading [bar, psi, kPa, etc.]
Output = digital pressure reading [Vdc]

Example: Calculate the pressure for a -1 psi to 1 psi gage sensor with a 10 % to 90 % calibration, and a pressure output of 2.805 Vdc at 3.3 Vdc supply voltage:

$\text{Output}_{max.}$ = 2.97 Vdc (90 % of V_{supply})
$\text{Output}_{min.}$ = 0.33 Vdc (10 % of V_{supply})
$P_{max.}$ = 1 psi
$P_{min.}$ = -1 psi
Pressure = pressure in psi
Output = 2.805 Vdc

$$\text{Pressure} = \left(\frac{(2.805 - 0.33) * (1 - (-1))}{2.97 - 0.33}\right) + (-1)$$

$$\text{Pressure} = \left(\frac{4.95}{2.64}\right) - 1$$

$$\text{Pressure} = 0.875 \text{ psi}$$

Downloaded from Arrow.com.

9.0 RECOMMENDED PNEUMATIC SENSOR CONNECTIONS

9.1 TUBING

Tubing is a common method of pneumatically connecting to the sensors and needs to be matched to the sensor's application to provide the required operating temperature range and working pressure. Depending on the working pressure range and operating temperature, the corresponding type of tubing can be selected (i.e., Superthane®, silicone, and vinyl). Silicone tubing, for instance, tends to be the easiest to which to connect; however, its working pressure is not as high as that of the other materials.

The lower the shore rating for the tubing, the easier it is to insert the tubing onto the sensor's pressure port; however, the lower shore rated tubing also has lower working pressures. For working pressures of 20 psi and below, silicone or vinyl tubing tends to be used. For pressures above 20 psi, Superthane® or low-density polyethylene tubing may be considered. Table 29 shows recommended tubing for use with the Honeywell Basic Board Mount Pressure Sensors.

Generally, when the working pressure is 15 psi or less, clamps are typically not required. However, because each application is different, the end use must be taken into account before determining whether clamps are necessary to ensure that the tubing remains in place and doesn't leak. Considerations include vibration, pressure spikes, and the type of tubing being used. A common clamping method is to use a plastic cable tie, available in a variety of sizes and found in most hardware stores. They are relatively easy to install and stay in place over time.

NOTICE

Instead of using a clamp, a small drop of epoxy may be applied to either pressure port prior to the tubing being placed onto the port or applied at the end of the tubing once the tubing is in place. This method holds the tubing in place and can further act as a sealing agent to help ensure a leak-tight connection between the pressure port and the tubing. A room temperature sealant is generally used for this purpose. Ensure that the epoxy doesn't block the hole in the port as it needs to remain open.

NOTICE

To apply a more rigid tubing-to-port connection, a low-power heat gun may be used to slightly heat the tubing. Once cooled, the tubing tends to grip the pressure port better.

TABLE 29. RECOMMENDED TUBING

Pressure Port	Manufacturer	Type	Part Number	ID	OD	Pressure at 25°C (psi)
AN	Frelin-Wade	Fre-Thane® (polyurethane)	1A-156-11	0.093 in	0.156 in	210
AN	Frelin-Wade	nylon	1A-200-01	0.093 in	0.125 in	270
AN	NewAge Industries	PVC	1100225	0.094 in	0.156 in	42
AN	NewAge Industries	silicone	2800315	0.094 in	0.156 in	20
AN	McMaster	silicone	5041K512	2,0 mm	6,0 mm	60
AN	McMaster	silicone	5041K601	2,0 mm	6,0 mm	115
RN, RR	Frelin-Wade	Fre-Thane	95a-157	0.066 in	0.125 in	225
RN, RR	NewAge Industries	Superthane® (ether)	2110535	0.066 in	0.125 in	135
RN	NewAge Industries	silicone	2800161	0.063 in	0,188 in	20
RN, RR	Du-Bro	silicone	196 1/16 ID	0.063 in	0.125 in	20
RN, RR	US Plastics	Excelthane polyurethane	77901710	0.063 in	0.125 in	70
RN, RR	McMaster	silicone	5041K603	1,0 mm	3.00 in	15
DA	McMaster	silicone	5041K512	2,0 mm	6,0 mm	60


Downloaded from Arrow.com.

9.2 O-RING MANIFOLD DESIGNS


O-rings may also be used to connect pneumatically to the sensor. Most O-ring manufacturers recommend a compression of 20 % to 25 % to provide the proper O-ring compression over the temperature range. Silicone or fluorosilicone O-rings are commonly used as they tend to take less of a set over temperature verses other O-ring materials. System operating temperatures and sealant media compatibility are the two most important parameters which must be considered when selecting an O-ring base polymer. See Figures 20 and 21, and Table 30 for more information.

Figure 20. Guidelines for O-ring Manifold Designs[1]


NN Pressure Port




VN Pressure Port[2]



AN Pressure Port




SN Pressure Port[2]



[1] The recommended design has been validated for operating conditions ranging from -40°C to 110°C and up to 16 bar gage pressure.
[2] For more demanding applications, a second O-ring can be used with a gland height of 3,6 mm (VN pressure port) and 4,55 mm (SN pressure port).

Figure 21. Force vs. % of O-ring Compression for N Port Type



NOTICE
It is the buyer's sole responsibility to determine the suitability of the product in the application.

Downloaded from Arrow.com.

TABLE 30. RECOMMENDED O-RINGS

Pressure Port	O-ring size AS-568 uniform dash numbers	O-ring ID (mm)	O-ring C/S (mm)	Material	Supplier	Part Number	Shore Hardness
NN	-004	1,78	1,78	Fluoroelastomer	McMaster	8333T114	Durometer 70A
NN	-004	1,78	1,78	Silicone	McMaster	1283N14	Durometer 70A
AN	-004	1,78	1,78	Fluoroelastomer	McMaster	8333T114	Durometer 70A
AN	-004	1,78	1,78	Silicone	McMaster	1283N14	Durometer 70A
SN	-005	2,57	1,78	Fluoroelastomer	McMaster	8333T115	Durometer 70A
SN	-005	2,57	1,78	Silicone	McMaster	1283N15	Durometer 70A
VN	-006	2,90	1,78	Fluoroelastomer	McMaster	8333T116	Durometer 70A
VN	-006	2,90	1,78	Silicone	McMaster	1283N16	Durometer 70A

Downloaded from Arrow.com.


O-rings may also be used to connect pneumatically to the sensor. Most O-ring manufacturers recommend a compression of 20 % to 25 % to provide the proper O-ring compression over the temperature range. Silicone or fluorosilicone O-rings are commonly used as they tend to take less of a set over temperature verses other O-ring materials. System operating temperatures and sealant media compatibility are the two most important parameters which must be considered when selecting an O-ring base polymer. See Figures 22 and 23, and Table 31 for more information.

NOTICE

It is the buyer's sole responsibility to determine the suitability of the product in the application.

Figure 22. Guidelines for O-Ring Manifold Designs

NX Pressure Port



VX Pressure Port[1]






Figure 23. Force v. % of O-ring Compression for N Port Type



SX Pressure Port[2]



[1] The recommended design has been validated for operating conditions ranging from -40 °C to 110 °C and up to 16 bar guage pressure.

[2] For more demanding applications, a second O-ring can be used with a gland height of 3,6 mm (VN pressure port) and 4,55 mm (SN pressure port).

TABLE 31. RECOMMENDED O-RINGS

Pressure Port	O-ring size AS-568 uniform dash numbers	O-ring ID (mm)	O-ring C/S (mm)	Material	Supplier	Part Number	Shore Hardness
NN	-004	1,78	1,78	Fluoroelastomer	McMaster	8333T114	Durometer 70A
NN	-004	1,78	1,78	Silicone	McMaster	1283N14	Durometer 70A
SN	-005	2,57	1,78	Fluoroelastomer	McMaster	8333T115	Durometer 70A
SN	-005	2,57	1,78	Silicone	McMaster	1283N15	Durometer 70A
VN	-006	2,90	1,78	Fluoroelastomer	McMaster	8333T116	Durometer 70A
VN	-006	2,90	1,78	Silicone	McMaster	1283N16	Durometer 70A

Downloaded from Arrow.com.

⚠ WARNING
PERSONAL INJURY

DO NOT USE these products as safety or emergency stop devices or in any other application where failure of the product could result in personal injury.

Failure to comply with these instructions could result in death or serious injury.

⚠ WARNING
MISUSE OF DOCUMENTATION

- The information presented in this product sheet is for reference only. Do not use this document as a product installation guide.
- Complete installation, operation, and maintenance information is provided in the instructions supplied with each product.

Failure to comply with these instructions could result in death or serious injury.

WARRANTY/REMEDY

Honeywell warrants goods of its manufacture as being free of defective materials and faulty workmanship during the applicable warranty period. The Honeywell standard product warranty applies unless agreed to otherwise by Honeywell in writing; please refer to your order acknowledgment or consult your local sales office for specific warranty details. If warranted goods are returned to Honeywell during the period of coverage, Honeywell will repair or replace, at its option, without charge those items that Honeywell, in its sole discretion, finds defective. **The foregoing is buyer's sole remedy and is in lieu of all other warranties, expressed or implied, including those of merchantability and fitness for a particular purpose. In no event shall Honeywell be liable for consequential, special, or indirect damages.**

While Honeywell may provide information or engineering support for its products through Honeywell personnel, literature and website, it is the buyer's sole responsibility to determine the suitability of the Honeywell product(s) for the buyer's requirements

Specifications may change without notice. The information we supply is believed to be accurate as of this writing. However, Honeywell assumes no responsibility for its use.

For more information

Honeywell Sensing Solutions services its customers through a worldwide network of sales offices and distributors. For application assistance, current specifications, pricing, or the nearest Authorized Distributor, visit automation.honeywell.com/hss or call:

USA/Canada	+302 613 4491
Latin America	+1 305 805 8188
Europe	+44 1344 238258
Japan	+81 (0) 3-6730-7152
Singapore	+65 6355 2828
Greater China	+86 4006396841

Honeywell Sensing Solutions
830 East Arapaho Road
Richardson, TX 75081
www.honeywell.com

Fre-Thane® is a registered trademark of Freelin-Wade Co.
Superthane® is a registered trademark of NewAge® Industries.

32350268-I-EN | I | 10/25
© 2025 Honeywell International Inc. All rights reserved.

Honeywell

Downloaded from Arrow.com.