




MODEL SC50**DIGITAL ELECTRONIC SCALE****Scale Description**

- A. Displayed reading on LCD
B. Power ON/OFF button
C. UNITS button
D. ZERO (TARE) button
E. Battery compartment

Button Descriptions

1. Press POWER button to switch ON
2. Press UNIT to select weight units (lbs. or kg.)
3. Press ZERO to null the displayed value

Battery Replacement


Pull out the battery drawer and replace the CR2032 battery observing correct polarity (see diagram). To close, push the battery drawer firmly into place. Please dispose of batteries responsibly.

Weighing

Refer to the numbered diagram below for these seven steps:

1. Press the power button. With no stress on the scale, the LCD should indicate 0.00. Press the ZERO button if necessary.
2. Press the UNIT button to select lbs. or kg.
3. See diagram below. Strap the webbing belt (C) through the handle (D) and secure the belt hook (A) onto the triangle ring (B).
4. Lift the scale gently. Ensure that the scale is horizontal and balanced. The scale will beep and the weight display will freeze when the measurement stabilizes.
5. The weight display will hold for approx. 30 seconds and then the meter will power off automatically.
6. Long press the power button > 3 seconds to power OFF manually.
7. Tare: Weigh an object (luggage, container, etc.) and then press ZERO. Add additional weight. The scale will now display the net weight (content weight minus the luggage weight).

- A. Hook
B. Triangle ring
C. Webbing belt
D. Handle

**Safety**

- Do not overload the scale; damage to the scale can result. If overloaded (>5% max. weight), 'EEEE' will appear on the LCD.
- Remove the battery when storing the scale for > 60 days.
- Do not allow children to handle this device.

Specifications

Display	Color LCD, 4-digits 1.3cm (0.5") height
Weight Range	0.3kg. ~ 50kg. (0.7 ~ 110.2 lbs.)
Overload	'EEEE' indication
Resolution	0.05kg. (0.11 lbs.)
Accuracy	$\pm 0.25\text{kg. (0.55 lbs.)} < 20\text{kg. (44.1 lbs.)}$ $\pm 0.50\text{kg. (1.10 lbs.)} > 20\text{kg. (44.1 lbs.)}$
Battery	1 x CR2032 (3V)
Battery life	500 power on/off cycles
Product weight	80g (2.8 oz.) with battery
Dimensions	Scale: 62 x 62 x 45mm (2.4 x 2.4 x 1.8") LCD: 31 x 31mm (1.2 x 1.2"); Strap 23.9cm (9.4")
Safety	CE
Warranty	1 year

Copyright © 2015-2018 FLIR Systems, Inc.

All rights reserved including the right of reproduction in whole or in part in any form

www.extech.com