

Assembly Instructions

CT3274 & CT3275 Rolling Lead Racks

Tools Needed:

- Adjustable Wrench
- 4 mm Hex (Allen) Wrench

Steps:

1. Remove hardware from tray.



2. Turn extension pole upside down and press 5 castor assembly on pole end.



3. Insert bolt and washer and thread into pole. Tighten securely with adjustable wrench.



Assembly Instructions

CT3274 & CT3275 Rolling Lead Racks

4. Turn stand and castor assembly right side up. Place lead tray on stand platform and line up 4 holes.



5. Insert 4 screws into holes.



6. Place washers and nuts on screws and tighten lightly.

